

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010368/T1GA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070068314

Claimant
Vehicle No : SH9732U **Insured Vehicle No :** SGU6936S

Date of Loss: 27/09/2020 Nature of Claim: TP Claim No: 2438338793SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9732U	Engine No:	2ZRS063492
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FUX03564090
Reg. Date:	20/09/2017 (Man. Year: 2017)	Odometer:	429081 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,455.40	597.55	857.85	58.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	850.00	390.00	31.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,695.40	1,447.55	1,247.85	46.30
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	2,695.40	1,150.00	1,545.40	57.33
+ GST 7.00/7.00% (S\$)	188.68	80.50	108.18	57.34
Nett Amount (S\$)	2,884.08	1,230.50	1,653.58	57.33
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.40/day) (S\$)		376.20		
(S\$)		1,756.70		
Liabile Amount (50.00%) (S\$)		878.35		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		880.35		
Global Sum Settlement (S\$)		850.00		

INSPECTION

Date of Assignment: 28/09/2020

Date Inspected: 28/09/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	499.90 FL	*499.90 FL
2	1		*FRONT BUMPER BRKT RH	Cracked	77.00 FL	*77.00 FL
3	1		*FRONT FENDER SHIELD RH	Not Necessary	198.50 FL	*- FL
4	1		*FRONT FENDER RH	Repair	945.30 FL	*- FL
5	1		*FRONT FENDER (HYBRID) RH	Necessary	86.50 FL	*86.50 FL
6	1		*FRT FENDER ADV STICKER RH	Cut	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,907.20	763.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	451.80	165.85
Total Parts (\$\$)	1,455.40	597.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	420.00
2	SPRAYPAINT CHARGE	New	500.00	400.00
3	TUFF COAT ON AFFECTED PARTS 40	New	40.00	30.00
Gross Labour Cost (\$\$)			1,240.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >