

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20010370/ARS3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900120046

Claimant
Vehicle No : SKT9987H **Insured Vehicle No :** SMD1489S

Date of Loss: 25/09/2020 Nature of Claim: TP Claim No: 8754109677SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9987H**

Make & Model: HYUNDAI DM SANTA FE, 2.4 L GDI ABS/AB SR Engine No: G4KJFU007471
4WD 5DR (A)

Reg. Date: 27/06/2015 (Man. Year: 2015) Chassis No: KMHSU81BSFU492793

Colour: White Odometer: 142278 km

Engine Capacity: 2359 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R19 Rear Tyre Size: 255/50 R19
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,751.68	4,850.08	3,901.60	44.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,780.00	1,700.00	48.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,231.68	6,630.08	5,601.60	45.80
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	12,231.68	5,300.00	6,931.68	56.67
+ Car Rental (8.0 x S\$150.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,507.45		

INSPECTION

Date of Assignment: 29/09/2020

Date Inspected: 29/09/2020 Inspected At: Fong Motors - Kaki Bukit (HQ)
1 KAKI BUKIT AVE 6 #01-27/01-45
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,623.00 FL	*1,938.00 FL
2	2		*REAR TAILGATE SENSOR	Not Necessary	470.00 FL	*- FL
3	1		*REAR TAILGATE MECHANISM LOCK	Damaged	677.00 FL	*495.00 FL
4	1		*REAR TAILGATE ELECTRONIC SWITCH	Not Necessary	380.00 FL	*- FL
5	1		*REAR TAILGATE RUBBER WEATHERSTRIP	Cut	182.50 FL	*182.50 FL
6	1		*REAR TAILGATE WINDSCREEN RUBBER MOULDING	Necessary	115.00 FL	*115.00 FL
7	1		*REAR TAILGATE LOGO EMBLEM	Necessary	38.70 FL	*38.70 FL
8	1		*REAR TAILGATE SANTE EMBLEM	Necessary	42.50 FL	*42.50 FL
9	1		*REAR TAILGATE 4WD EMBLEM	Necessary	35.50 FL	*35.50 FL
10	1		*REAR TAILGATE INNER TRIMBOARD	Cracked	242.60 FL	*242.60 FL
11	1		*REAR BUMPER	Deformed	868.00 FL	*485.00 FL
12	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	398.80 FL	*398.80 FL
13	1		*REAR BUMPER CHROME GARNISH	Bent	385.80 FL	*385.80 FL
14	4		*REAR BUMPER PARKING SENSOR	Damaged (2 PCS ONLY)	819.20 FL	*409.60 FL
15	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	465.00 FL	*- FL
16	1		*REAR BUMPER LOWER GARNISH	Deformed	590.50 FL	*590.50 FL
17	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	85.60 FL	*85.60 FL
18	1		*REAR BUMPER TOWING COVER	Not Necessary	28.50 FL	*- FL
19	1		*REAR END PANEL	Repair	739.10 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	118.00 FL	*- FL
21	1		*REAR EXHAUST SILENCER BOX	Not Necessary	862.20 FL	*- FL
22	2		*REAR EXHAUST SILENCER BOX RUBBER MOUNTING	Not Necessary	129.60 FL	*- FL
23	1		*REAR END PANEL ANTENNA SENSOR	Damaged	125.00 FL	*125.00 FL
24	1		*REAR END PANEL BUZZER	Damaged	85.00 FL	*85.00 FL
25	1		*REAR BUMPER LOWER DIFFUSER (SILVER)	Deformed	295.00 FL	*295.00 FL
26	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
27	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,912.10	6,040.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,160.42	1,190.02
Total Parts (\$\$)	8,751.68	4,850.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING	New	60.00	30.00
2	TO REMOVE & REFIX REVERSE SENSOR ASSY AND RETIFY FOR PROPER FUNCTIONING	New	80.00	50.00
3	TO DIAGNOSE ,REPLACE /OR REPAIR TO RETIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AND WHERE CONSISTENT TO THE ACCIDENT	New	100.00	0.00
4	TO REMOVE REINSTALL REAR TAILGATE WINDSCREEN (TO FR)	New	150.00	120.00
5	TO REMOVE ,REINSTALL ROOF TOP UPHOLSTERY ,TRIM GARNISH , TRIM LINER CARPET (TO FR)	New	120.00	60.00
6	TO TRANSFER TAILGATE MECHANISM & WIRING ASSY (TO FR)	New	100.00	60.00
7	TO RESPRAY ,PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
8	TO REMOVE & REFIX EXHAUST SILENCER BOX ,REALIGN AND WHERE CONSISTENT TO THE ACCIDENT	New	100.00	0.00
9	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE DAMAGED BODYPARTS,REPAIR ,ALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
10	TO SET ON CHASSIS BENCH ,ADJUST & ALIGN REAR CHASSIS	New	250.00	0.00
11	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED & REPLACED PANEL AND WHERE CONSISTENT TO THE ACCIDENT	New	120.00	60.00
Gross Labour Cost (\$\$)			3,480.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >