Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010372/UGA3Q2

**Date:** 15/01/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070029930

Claimant
Vehicle No: FBE892S Insured Vehicle No: SGL322A

Date of Loss: 19/09/2020 Nature of Claim: TP Claim No: 5191370418SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBE892S

 Make & Model:
 YAMAHA T135, 135cc
 Engine No:
 5YP301446

 Reg. Date:
 13/11/2009 (Man. Year: 2009)
 Chassis No:
 5YP301446

 Colour:
 Red
 Odometer:
 94453 km

Engine Capacity: 135 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 70-90-17 Rear Tyre Size: 80-90-17
Front Left Side: Maxxis 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,017.90	1,223.80	1,794.10	59.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	250.00	610.00	70.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,877.90	1,473.80	2,404.10	61.99
Approved Total (Overridden) (S\$)		1,150.00		
Nett Amount (S\$)	3,877.90	1,150.00	2,727.90	70.34
+ Loss of Use (6.0 x S\$	20.00/day) (S\$)	120.00		

**Nett Liability (S\$)** 

**INSPECTION** 

Date of Assignment: 28/09/2020

Date Inspected: 28/09/2020 Inspected At: Erofia Motor Trading Pte Ltd (KAKI

BUKIT)

1,270.00

1 KAKÍ BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Repair	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*-FL
3	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*-FL
4	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*-FL
5	1		*HANDLE -BAR	Bent	88.00 FL	*88.00 FL
6	1		*SET SIDE MIRRORS	Cut	110.00 FL	*110.00 FL
7	1		*CLUTCH LEVER	Scratched	32.00 FL	*32.00 FL
8	2		*FRONT SIGNALS	Not Necessary	140.00 FL	*-FL
9	1		*HEADLAMP	Not Necessary	185.00 FL	*-FL
10	1		*SET FAIRING ASSY	Cut	525.00 FL	*525.00 FL
11	1		*FRONT FOOTREST BRACKET	Bent	65.00 FL	*65.00 FL
12	2		*FRONT FOOTREST RUBBER -R/H	Torn	70.00 FL	*70.00 FL
13	1		*GEAR PEDAL	Bent	42.00 FL	*42.00 FL
14	2		*REAR FOOTREST	Serviceable	80.00 FL	*-FL
15	2		*REAR FOOTREST BRACKET	Not Necessary	156.00 FL	*-FL
16	1		*SIDE STAND	Repair	75.00 FL	*-FL
17	1		*MAIN STAND	Repair	95.00 FL	*-FL
18	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*-FS
19	2		*FORK OILS	Not Necessary	30.00 FS	*-FS
20	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*-FS
21	1		*SET STEERING CONE	Necessary	90.00 FS	*90.00 FS
22	1		*REAR BOX	Cut	120.00 FS	*120.00 FS
23	1		*FRONT TYRE	Not Necessary	180.00 FS	*-FS
24	1		*ERP IU UNIT	Cut / Shorted	200.00 FS	*175.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.			
				Sub Total (S\$)	3,275.00	1,317.00
	- List Item Discount on L Items 10.00/10.00% (S\$)		257.10	93.20		
				Total Parts (S\$)	3,017.90	1,223.80
Γ	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	250.00
4	TO REPAIR BODY FRAME	New	350.00	0.00
	Gross Labour Cost (S\$)		860.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >