

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20010373/AES3Q2
Date: 03/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	GBB5096G	Insured Vehicle No :	SHC1771R
Date of Loss:	27/09/2020	Nature of Claim:	TP
		Claim No:	MCT20090441

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB5096G	Engine No:	1KD1921538
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P400042120
Reg. Date:	13/05/2009 (Man. Year: 2009)	Odometer:	308010 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,357.08	4,096.36	2,260.72	35.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,940.00	770.00	28.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,067.08	6,036.36	3,030.72	33.43
Approved Total (Overridden) (S\$)		4,800.00		

(S\$)	9,067.08	4,800.00	4,267.08	47.06
+ GST 7.00/7.00% (S\$)	634.70	336.00	298.70	47.06
Nett Amount (S\$)	9,701.78	5,136.00	4,565.78	47.06
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		5,778.45		

INSPECTION

Date of Assignment: 28/09/2020

Date Inspected: 29/09/2020

Estimated Period of Repair: 6.0 days

Inspected At:

N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
 KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18
 Singapore 417921

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Jan 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB5096G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	695.90 FL	*695.90 FL
2	4		*REAR BUMPER LOWER BRACKET	Bent (2 PCS ONLY)	120.00 FL	*60.00 FL
3	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	121.74 FL	*121.74 FL
4	1		*REAR END PANEL (INNER)	Dented	859.50 FL	*859.50 FL
5	1		*REAR END PANEL (OUTER)	Dented	388.27 FL	*388.27 FL
6	1		*REAR END PANEL TOP PLATE	Not Necessary	180.71 FL	*- FL
7	2		*REAR END PANEL TOP PLATE SIDE COVER L/R	Not Necessary	76.50 FL	*- FL
8	1		*REAR LH FENDER	Repair	1,087.58 FL	*- FL
9	1		*REAR LH FENDER INNER AIR VENT	Cracked	58.00 FL	*58.00 FL
10	1		*REAR TAILGATE	Dented	1,890.54 FL	*1,890.54 FL
11	1		*REAR TAILGATE LOGO EMBLEM	Necessary	85.87 FL	*85.87 FL
12	2		*REAR TAILGATE HINGES L/R	Not Necessary	193.14 FL	*- FL
13	1		*REAR TAILGATE INNER LOCK CONTROL ASSY	Not Necessary	290.95 FL	*- FL
14	2		*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	97.40 FL	*- FL
15	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	68.57 FL	*- FL
16	1		*REAR TAILGATE MECHANISM LOCK	Damaged	235.00 FL	*235.00 FL
17	1		*REAR TAILGATE WEATHERSTRIP	Cut	395.90 FL	*395.90 FL
18	1		*REAR TAILLAMP L/R	N/S Cracked	791.60 FL	*395.80 FL
19	1		*REAR TAILLAMP LOWER GARNISH L/R	N/S Deformed	177.26 FL	*88.63 FL
20	2		*REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R	Not Necessary	101.68 FL	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*REAR TAILGATE 70KM STICKER	Necessary	25.00 FS	*15.00 FS
23	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
25	1		*SET REAR TAILGATE OUTER HANDLE CLIPS	Not Necessary	30.00 FS	*- FS
26	1		*REAR TAILGATE WINDSCREEN SEAL	Necessary	80.00 FS	*40.00 FS
27	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*REAR TAILLAMP CLIPS L/R - 1 SET	Necessary	50.00 FS	*15.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	8,336.11
					- List Item Discount on L Items 25.00/25.00% (\$)	1,979.03
					Total Parts (\$)	6,357.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	50.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	50.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
Gross Labour Cost (S\$)			2,710.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >