

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20010377/AGS3Q2  
**Date:** 25/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SMJ2404Z	<b>Insured Vehicle No :</b>	SHD4482A
Date of Loss:	26/09/2020	Nature of Claim:	TP
		Claim No:	MCT20090399

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMJ2404Z</b>		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT ABS (A)	Engine No:	L15B6001590
Reg. Date:	26/02/2019 (Man. Year: 2018)	Chassis No:	GK82001286
Colour:	Blue	Odometer:	136742 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,415.28	4,208.56	4,206.72	49.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,410.00	1,600.00	53.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,425.28</b>	<b>5,618.56</b>	<b>5,806.72</b>	<b>50.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		

(S\$)	11,425.28	4,500.00	6,925.28	60.61
<b>+ GST 7.00/7.00% (S\$)</b>	799.77	315.00	484.77	60.61
<b>Nett Amount (S\$)</b>	<b>12,225.05</b>	<b>4,815.00</b>	<b>7,410.05</b>	<b>60.61</b>
<b>+ Loss of Use (8.0 x S\$60.00/day) (S\$)</b>		480.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		100.00		
<b>Nett Liability (S\$)</b>		<b>5,402.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,400.00</b>		

INSPECTION

Date of Assignment: 28/09/2020

Date Inspected: 29/09/2020

Inspected At:

N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)  
 KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18  
 Singapore 417921

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 28 Jan 2021)		
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 G CVT ABS (A) (Model not available in database)	
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ2404Z)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.		

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,050.00 FL	*1,050.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Deformed	140.00 FL	*140.00 FL
3	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	145.00 FL	*- FL
4	1		*FRONT BUMPER RH FOG LAMP	Cracked	308.90 FL	*308.90 FL
5	1		*FRONT BUMPER RH FOG LAMP GARNISH	Deformed	95.00 FL	*95.00 FL
6	1		*FRONT BUMPER SIDE RETAINER L/R	O/S Damaged	24.00 FL	*12.00 FL
7	1		*FRONT BUMPER TOW HOOK COVER	Deformed	25.00 FL	*25.00 FL
8	1		*FRONT CHASSIS SIDE MEMBER RH (INNER)	Repair	75.50 FL	*- FL
9	1		*FRONT CHASSIS SIDE MEMBER RH (OUTER)	Repair	65.50 FL	*- FL
10	1		*FRONT GRILLE	Cracked	395.00 FL	*395.00 FL
11	1		*FRONT GRILLE OUTER CHROME COVER	Not Necessary	302.50 FL	*- FL
12	1		*FRONT GRILLE OUTER CHROME COVER LOGO EMBLEM	Necessary	23.40 FL	*23.40 FL
13	1		*FRONT HEADLAMP (LED) L/R	O/S Cracked	4,500.00 FL	*2,250.00 FL
14	1		*FRONT HEADLAMP LOWER BRACKET L/R	O/S Cracked	76.00 FL	*38.00 FL
15	1		*FRONT RH EXTENSION PANEL (INNER)	Buckled	94.80 FL	*94.80 FL
16	1		*FRONT RH EXTENSION PANEL (OUTER)	Buckled	150.00 FL	*150.00 FL
17	1		*FRONT RH FENDER	Dented	368.10 FL	*368.10 FL
18	1		*FRONT RH FENDER INNER SHIELD	Deformed	110.50 FL	*110.50 FL
19	1		*FRONT RH KNUCKLE ARM	Not Necessary	330.60 FL	*- FL
20	1		*FRONT RH KNUCKLE ARM BEARING	Not Necessary	168.00 FL	*- FL
21	1		*FRONT RH SHOCK ABSORBER	Not Necessary	420.00 FL	*- FL
22	1		*FRONT SUPPORT LOWER PANEL	Repair	180.30 FL	*- FL
23	1		*WASHER TANK	Cracked	75.00 FL	*75.00 FL
24	1		*WASHER TANK MOTOR	Not Necessary	58.50 FL	*- FL
25	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
26	1		*SET FRONT BUMPER LOWER SPOILER CLIPS	Not Necessary	30.00 FS	*- FS
27	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		<b>*SET FRONT RH FENDER INNER SHIELD CLIPS</b>	Necessary	50.00 FS	*30.00 FS
29	1		<b>*FRONT RH SPORT RIM</b>	Not Necessary	580.00 FS	*- FS
30	1		<b>*FRONT RH TYRE</b>	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>10,251.60</b>	<b>5,235.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	1,836.32	1,027.14
<b>Total Parts (S\$)</b>	<b>8,415.28</b>	<b>4,208.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING (TO FR)	New	80.00	30.00
2	TO REMOVE ,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB ,DRIVE SHAFT ,ANTI-ROLL BAR ,TOP -ARM AND STEERING RACK AND PINION	New	150.00	0.00
3	TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	600.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,010.00</b>	<b>1,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >