

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010382/KES3Q2

Date: 08/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SHD363L

Insured Vehicle No : SFP50A

Date of Loss: 24/09/2020

Nature of Claim: TP

Claim No: 1381950120SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD363L**

Make & Model: RENAULT LATITUDE, 2.0 L DCI (A)

Engine No: M9R8839C002727

Reg. Date: 17/05/2016 (Man. Year: 2015)

Chassis No: VF1ABL15AUC282719

Colour: Metallic White/Red

Odometer: 397182 km

Engine Capacity: 1995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Sailun 9 mm

Rear Left Side:

Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side:

Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,595.73	1,702.13	11,893.60	87.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	1,185.00	2,765.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,545.73	2,887.13	14,658.60	83.55
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	17,545.73	2,300.00	15,245.73	86.89
+ GST 7.00/7.00% (S\$)	1,228.20	161.00	1,067.20	86.89
Nett Amount (S\$)	18,773.93	2,461.00	16,312.93	86.89
+ Car Rental (3.0 x S\$81.13/day) (S\$)		243.39		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,711.88		
Global Sum Settlement (S\$)		2,710.00		

INSPECTION

Date of Assignment: 25/09/2020

Date Inspected: 25/09/2020 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled/Mtg Cracked	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
3	1		*BUMPER RETAINER FRT RH	Distorted	101.40 FL	*101.40 FL
4	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
5	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
6	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
7	1		*HEADLAMP RH	Serviceable	743.60 FL	*- FL
8	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
9	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
10	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	*- FL
11	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
12	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
13	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
14	1		*FRAME FULL SUPPORT PANEL	Repair	592.70 FL	*- FL
15	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
16	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
17	1		*SUBFRAME OUTER FRT	Serviceable	1,094.20 FL	*- FL
18	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
19	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
20	1		*DOOR HINGE UPPER FRT RH	Repair	261.28 FL	*- FL
21	1		*DOOR HINGE LOWER FRT RH	Repair	300.55 FL	*- FL
22	1		*DOOR SEAL FRT RH	Serviceable	72.82 FL	*- FL
23	1		*DOOR WEATHERSTRIP FRT RH	Serviceable	410.27 FL	*- FL
24	1		*BUMPER CLIP FRT	Necessary	90.00 FS	*90.00 FS
25	1		*BUMPER RETAINER CLIP FRT	Not Necessary	75.00 FS	*- FS
26	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	75.00 FS	*- FS
27	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
28	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	45.00 FS	*- FS
29	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	50.00 FS	*- FS
30	1		*WHEELARCH CLIP FRT	Not Necessary	75.00 FS	*- FS
31	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
32	1		*FRONT RENAULT TYRE RIM	Dented	380.00 FS	*380.00 FS
33	1		*SET RADIATOR GRILLE SCREW	Not Necessary	55.00 FS	*- FS
34	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	60.00 FS	*- FS
35	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
36	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
37	1		*ROCKER PANEL CLIP	Not Necessary	60.00 FS	*- FS
38	1		*DOOR SEAL CLIP	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,954.14 1,830.70
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,358.41 128.57

Total Parts (\$\$) 13,595.73 1,702.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
2	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	660.00
4	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,200.00	400.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	20.00
6	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING	New	380.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
Gross Labour Cost (\$\$)			3,950.00	1,185.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >