



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 3820B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER FRT	DEFORMED	1,218.90	1,218.90
1	BUMPER SIDE RETAINER L/H FRT	NOT NECESSARY	189.20	-
1	BUMPER SIDE GARNISH L/H FRT	DEFORMED	578.10	578.10
1	FENDER INNER SHIELD L/H FRT	TORN	378.20	342.80
7	FENDER INNER SHIELD CLIPS FRT @\$5.80	NECESSARY	40.60	40.60
	LESS 25% DISCOUNT		-601.25	-545.10
			1,803.75	1,635.30
<u>LABOUR</u>				
	REMOVE & REPLACE ACCIDENT DAMAGED PARTS.		600.00	400.00
	SPRAY PAINTING ACCIDENT EFFECT PARTS.		600.00	400.00
	CHECK ALL LIGHTING AFTER REPAIR.		60.00	30.00
			1,260.00	830.00
GRAND TOTAL			3,063.75	2,465.30

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00
---	--	--	-----------------

Report Ref No. CC6/CHB20010383/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.