

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20010389/QPS3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0001471
Claimant Vehicle No :	SMB3616P	Insured Vehicle No :	SLM4038E
Date of Loss:	11/09/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001784

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB3616P		
Make & Model:	ALEXANDER DENNIS ENVIRO500, 8.8 D (A)	Engine No:	22158496
Reg. Date:	01/12/2015 (Man. Year: 2015)	Chassis No:	SFD76CLR5FMTL4098
Colour:	Silver	Odometer:	300379 km
Engine Capacity:	8849 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	305/70 R22.5	Rear Tyre Size:	305/70 R22.5
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,238.00	803.00	435.00	35.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,238.00	803.00	435.00	35.14
	+ Loss of Use (2.5 x S\$300.00/day) (S\$)	750.00		
	+ Doc/Search Fee (S\$)	7.00		
	Nett Liability (S\$)	1,560.00		

INSPECTION

Date of Assignment:	28/09/2020	
Date Inspected:	29/09/2020	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Oct 2020)	
Parts:	N/A	ALEXANDER DENNIS ENVIRO500 8.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB3616P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR RH FRONT PORTION	New	530.00	265.00
2	TO PUTTY & RESPRAY	New	708.00	538.00
Gross Labour Cost (S\$)			1,238.00	803.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >