

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010392/GGA3Q2**Date:** 18/07/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900103232
Claimant Vehicle No :	SLP932J	Insured Vehicle No :	SML6403P
Date of Loss:	23/09/2020	Nature of Claim:	TP
		Claim No:	8049442113SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP932J	Engine No:	H5FF408D223384
Make & Model:	RENAULT KADJAR, 1.2 TCE EDC 7AT S&S EU6 (A)	Chassis No:	VF1RFE00957210127
Reg. Date:	25/05/2017 (Man. Year: 2017)	Odometer:	63011 km
Colour:	White		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,058.00	2,227.50	2,830.50	55.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,470.00	720.00	32.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,248.00	3,697.50	3,550.50	48.99
+ GST 7.00/7.00% (S\$)	507.36	258.83	248.53	48.98
Nett Amount (S\$)	7,755.36	3,956.33	3,799.03	48.99
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		16.00		
Nett Liability (S\$)		4,507.33		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment:	28/09/2020	Chew Goon Motor (AMK)
Date Inspected:	29/09/2020 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	5.0 days	Singapore 568047

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Buckled	1,850.00 FL	*1,250.00 FL
2	1		*FRONT DOOR STICKER	Necessary	375.00 FL	*40.00 FL
3	1		*FRONT DOOR PROTECTOR	Scratched	440.00 FL	*220.00 FL
4	10		*FRONT DOOR PROTECTOR CLIPS	Necessary	100.00 FL	*20.00 FL
5	1		*FRONT DOOR PROTECTOR MOULDING	Scratched	320.00 FL	*120.00 FL
6	1		*FRONT DOOR INSULATION	Not Necessary	150.00 FL	*- FL
7	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	450.00 FL	*- FL
8	1		*FRONT DOOR LOWER RUBBER	Not Necessary	290.00 FL	*- FL
9	1		*FRONT DOOR TYRE PRESSURE STICKER	Necessary	25.00 FL	*15.00 FL
10	1		*FRONT DOOR INNER TRIM BOARD CLIPS (9 PCS)	Necessary	90.00 FL	*30.00 FL
11	2		*FRONT DOOR INNER TRIM BOARD RIYETS	Necessary	20.00 FL	*10.00 FL
12	1		*REAR DOOR PROTECTOR	Scratched	420.00 FL	*210.00 FL
13	10		*REAR DOOR PROTECTOR CLIPS	Necessary	100.00 FL	*20.00 FL
14	1		*REAR DOOR PROTECTOR MOULDING	Scratched	290.00 FL	*80.00 FL
15	1		*FRONT FENDER ARCH PROTECTOR	Scratched	290.00 FL	*210.00 FL
16	1		*FRONT FENDER ARCH PROTECTOR CLIPS (6 PCS)	Necessary	60.00 FL	*20.00 FL
17	1		*REAR FENDER ARCH PROTECTOR	Scratched	290.00 FL	*210.00 FL
18	1		*REAR FENDER ARCH PROTECTOR CLIPS (6 PCS)	Necessary	60.00 FL	*20.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,620.00	2,475.00
- List Item Discount on L Items 10.00/10.00% (S\$)	562.00	247.50
Total Parts (S\$)	5,058.00	2,227.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /TRANSFER FRONT DOOR FITTINGS /ANCILLARY ACCESSORIES	New	150.00	60.00
2	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	60.00	0.00
3	TO REPAIR /RESPRAY REAR WHEEL RIM	New	100.00	50.00
4	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
5	LABOUR CHARGE- PANEL BEATING ,REPAIRING OF FRONT FENDER ,REAR O/S DOOR ,REAR FENDER AND PARTS REPLACEMENT	New	600.00	400.00
6	TO RESPRAY AFFECTED AREAS (PEARL)	New	1,200.00	900.00
Gross Labour Cost (\$\$)			2,190.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >