

(08/11/13) wef  
ASS. REQ. BY: Marcus

REF: CS/GA120010402/4vd3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: **SMG 3239T**  
 at Workshop m/s **R.**  
 of \_\_\_\_\_  
 Insured: **GBB7636K**  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.  
 Bal. or Market Value: **6142k.**  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **4** days Res.: Yes or No  
 Lum Sum: **20** % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS **663F**  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

Veh No: **SMG 3239T** Yr Regn: **7 117**  
 Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or **W**  
 Make: **Mer Benz GLC 250 c.c** **1991**  
 Colour **Black** A/C: **Insured / Std / NI / NA**  
 Sp. Reading **94620** T/Radio: **Insured / Std / NI / NA**  
 Eng/No: \_\_\_\_\_  
 C/No: **WDC 2533462F 237498**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: **In order** / Jammed / Leaked / Burnt or  
 Brake: **In order** / Jammed / Leaked / Burnt or  
 Modi: **Nil** / S/Rim / STD A/Rim or  
 Tyre Size: F: **235/55 R19**  
 R: **255/50 R19**  
 BS / DUN / EXNOVA / GY / FS / LIZA **(M)** / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. **7** mm R/Bal. **7** mm  
 L/Bal. **7** mm L/Bal. **7** mm  
 D.O.A. **28/9/20** D.O.I. **29/9/20**  
 Survey held at \_\_\_\_\_  
 Des. of Damages: **FR** / Rear / O/S / N/S / U/C / Rooftop or  
**Rear**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
**29/10/20** LTA @ 81951 Netff 60049  
**9/10/20** M/s @ 9200 Confirmed with Alan (Red 16,528.42, 64%)

Date/Time, File Pass to?  : Preli. Report  : Final Report  
 Date/Time, File Return to?  
 2) 9/10/20-Typist  
 Report Format : TP  
 Lump Sum / L.B.: (\$ 9200 )  
 Days Of Repair: 4  
 Resurvey No. of Trip: 2  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ ) \_\_\_\_\_ S + RS, \_\_\_\_\_ SI  
 : Interview (\$ ) Photos  
 : Tech. Invs (\$ ) Others  
 : Weekend (\$ )  
 TOTAL

FASTECH AUTO PTE LTD  
 BLK 1 KAKI BUKIT AVE 6  
 #01-48 AUTOBAY  
 SINGAPORE 417883

Submit to us

Not Authorized  
 Male

28/5/20 1/5/2000  
 4 days.

VEHICLE NUMBER :SMG 3239T

1PC	TAILGATE	body		\$2,510.00	✓
1PC	TAILGATE REAR LOGO	scr		\$68.00	✓
1PC	TAILGATE 'GLC 250' ELBLEM	neu		\$92.00	✓
1PC	TAILGATE '4 MATIC' ELBLEM	neu		\$95.00	✓
2PCS	TAILGATE REFLECTORS @\$505.00	crs		\$1,010.00	✓
1PC	TAILGATE INNER LOCK	shaded	299.20	\$385.00	✓
1PC	TAILGATE INNER LOSS SENSOR	shaded/crs		\$399.00	✓
1PC	TAILGATE WEATHERSTRIP	neu	315.42	\$392.00	✓
1PC	REAR BUMPER TOP	20/20	1436.60	\$1,565.00	✓
1PC	REAR BUMPER CENTRE PAD	deform	492.11	\$825.00	✓
1PC	REAR BUMPER LOWER	11		\$655.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$85.00	11		\$170.00	X
1SET	REAR BUMPER RIVET	neu		\$60.00	✓
1PC	REAR BUMPER REINFORCEMENT	Benf	715.00	\$715.00	✓
2PCS	REAR BUMPER REFLECTORS @\$82.00	11		\$164.00	X
4PCS	REAR BUMPER PDC SENSORS @\$188.00	11		\$752.00	X
1PC	REAR BUMPER PDC WIRE	11		\$315.32	X
2PCS	REAR BUMPER INNER SIDE BRACKETS @\$95.00	11		\$190.00	X
1PC	REAR BUMPER SPONGE	MF		\$288.35	X
1PC	REAR BUMPER INNER KICKING SENSOR	crs		\$382.50	✓
1PC	REAR WINDSCREEN Moulding	neu	166.00	\$855.00	✓
1PC	REAR END PANEL	20/benf	1399.20	\$1,405.00	✓
1PC	REAR END PANEL TOP GARNISH	crs		\$306.00	✓
1PC	REAR FLOOR PANEL	11		\$1,485.00	X
2PCS	REAR FENDER OUTER PROTECTORS @\$399.00	Tom/mec 322x22644		\$798.00	✓
2PCS	REAR FENDER INNER TRIM BOARDS @\$960.00	11		\$1,920.00	X
2PCS	REAR EXHAUST CHROMES @\$480.00	11		\$960.00	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$466.25	X
1PC	REAR EXHAUST ASSY	11		\$1,850.00	X
				\$21,078.42	
	S.NETT				
1PC	REAR LICENCE PLATE W/HOLDER	11		\$50.00	X
1PC	REAR END PANEL SEALANT	neu		\$50.00	✓
1PC	REAR WINDSCREEN SEALANT	neu		\$50.00	40
1SET	REAR FLOOR PANEL INSULATOR	11		\$200.00	X
	TO CHECK WIRING			\$50.00	30
	TO DISMANTLR & REPLACED PDC SENSOR			\$80.00	50
	TO DISMANTLE & REFIX REAR WINDSCREEN			\$150.00	120
	TO TRANSFER TAILGATE MECHANISM			\$150.00	80
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY			\$150.00	80

(10%)

TO DISMANTLE & REPLACED REAR EXHAUST  
 TO SPRAY RUST PROOFING  
 TO RESET & REPROGRAMME SYSTEM  
 LABOUR FOR PANEL BEATING & REPLACED PARTS  
 TO PUTTY & SPRAY PAINTING

11 \$120.00 X  
 \$100.00 60  
 \$200.00 50  
 \$1,800.00 800  
 \$1,500.00 800  
 TOTAL \$25,728.42

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-10492.03  
 106  
 P-9441.02  
 S.W-90.00  
 L-2070.00  
 11601.02  
 200  
 9280