

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG20010407/UEA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800076198
<b>Claimant Vehicle No :</b>	FBL633L	<b>Insured Vehicle No :</b>	SMC3248M
Date of Loss:	31/08/2020	Nature of Claim:	TP
		Claim No:	6209241770SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBL633L</b>		
Make & Model:	SUZUKI UH200AL6 BURGMAN, 200cc ABS	Engine No:	H405402466
Reg. Date:	24/05/2016 (Man. Year: 2016)	Chassis No:	MLCC91121G0402466
Colour:	White	Odometer:	8163 km
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/90 R13	Rear Tyre Size:	130/70 R12
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,085.00	907.20	2,177.80	70.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	315.00	280.00	35.00	11.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,400.00</b>	<b>1,187.20</b>	<b>2,212.80</b>	<b>65.08</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>950.00</b>		
<b>(\$\$)</b>	3,400.00	950.00	2,450.00	72.06
<b>+ GST 7.00/7.00% (\$\$)</b>	238.00	66.50	171.50	72.06
<b>Nett Amount (\$\$)</b>	<b>3,638.00</b>	<b>1,016.50</b>	<b>2,621.50</b>	<b>72.06</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	29/09/2020		
Date Inspected:	29/09/2020	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER	Scratched	17.00 F	*17.00 FL
2	1		*BODY MUFFLER	Repair	1,724.00 F	*- FL
3	1		*BOX REAR (KAPPA) K42	Scratched	149.00 F	*149.00 FL
4	1		*CONNECTOR MUFFLER	Not Necessary	24.00 F	*- FL
5	1		*COVER SHIELD ,LEG FRONT (WHITE)	Cut	327.00 F	*327.00 FL
6	1		*COVER ,COMP MUFFLER FR	Cut	24.00 F	*24.00 FL
7	1		*COVER MUFFLER	Cut	76.00 F	*76.00 FL
8	1		*COVER MUFFLER RR	Cut	44.00 F	*44.00 FL
9	1		*FOOTBOARD RH (BLACK)	Cut	28.00 F	*28.00 FL
10	1		*HANDLE PILLION RIDER RH (WHITE)	Repair	136.00 F	*- FL
11	1		*LEVER ,FRONT BRAKE	Scratched	37.00 F	*37.00 FL
12	1		*MIRROR ASSY ,RR VIEW LH (CUT)	Not Consistent With The Impact	51.00 F	*- FL
13	1		*MIRROR ASSY ,RR VIEW RH	Cut	56.00 F	*56.00 FL
14	1		*MUDGUARD FRONT (WHITE)	Repair	142.00 F	*- FL
15	1		*SHIELD ,LEG LOWER (GRAY)	Cut	122.00 F	*122.00 FL
16	1		*SHIELD ,LEG SIDE RH (GRAY)	Cut	128.00 F	*128.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,085.00	1,008.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	100.80
Total Parts (S\$)	3,085.00	907.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	315.00	280.00
<b>Gross Labour Cost (\$)</b>			<b>315.00</b>	<b>280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >