

(08/11/13) Wef

ASS. REC. BY: *Marcus*

REF:

CS/CTI 20010409/U

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMQ2617P

at Workshop m/s

CRC 461 2m

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

075k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No: *SMQ2617P*

Yr Regn: *5/11/19*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(A)*

Make:

KIA STONIC

c.c

998

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp.Reading

13546

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAD 6811VL6325694

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

27/9/20

D.O.I.

30/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	LCV11428/Mr Bong Choon Siong (huang Junx
	Reg No/Reg Date	SMQ2617P / 05/11/2019
	Date In/Mileage	28/09/2020/ 13392
	Chassis-No	KNAD6811VL6325694
	Engine No	G3LCKP079266
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	ABTy / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	28/09/2020/ 16:41	DS	303/- Renemer	53860

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC/SCANNING				250.00
S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				100.00
S MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS				600.00
S MIPNT88088 TO REPLACE RHR TAIL LAMP,RHR BUMPER MLDG,LWR REAR BUMPER, REINFORCEMENT,BRACKETS,CLIP SENSOR,ETC				1800.00
S MIPNT88088 TO REPAIR RHR OUTER FENDER STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS				1260.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				
M KS 92402 H8 500	1.00	654.00	0.00	654.00
M KS 86682 H8 400	1.00	152.00	0.00	152.00
M KS 86610 H8 410	1.00	366.00	0.00	366.00
M KS 92406 H8 410	1.00	111.00	0.00	111.00
M KS 95720 H8 100	1.00	189.00	0.00	189.00
M KS 95720 H8 110	1.00	189.00	0.00	189.00
M KS 86631 H8 410	1.00	419.00	0.00	419.00
M KS 86642 H8 400	1.00	55.00	0.00	55.00
M KS 86614 H8 400	1.00	27.00	0.00	27.00
M KS 87742 H8 400	1.00	50.00	0.00	50.00
M KS 86822 H8 400	1.00	52.00	0.00	52.00
M KS 06032 50 037A	10.00	2.00	0.00	20.00
M KS 06032 50 037A	10.00	2.00	0.00	20.00
Z NOTES				
ACCIDENT ON 27/09/2020 ALONG TAMPINES AVENUE 10				
OWNER CLAIMING THIRD PARTY				
REQUIRED REPLACEMENT CAR				
TP#: GBH5862E TP INS: CHINA TAIPING				

Confirm & accepted by

p/p 3057.00

30/9/20
3 dy

Authorized signatory and company stamp

Parts

Labour

Standard Menu

Specialist Job

Others(Lub,etc)

Sundry

Total(w/o GST)

2,304.00

0.00

0.00

4,010.00

0.00

0.00

6,314.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name LCV11428/Mr Bong Choon Siong (huang Junx) Reg No/Reg Date SMQ2617P / 05/11/2019 Date In/Mileage 06/10/2020/ 13858 Chassis No KNAD6811VL6325694 Engine No G3LCKP079266 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim ABT / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	09/10/2020/ 17:24	DS	303 / Renemer	53860

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC/SCANNING				250.00
S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088 TO REPLACE RHR BUMPER MLDG, LWR REAR BUMPER, BRACKETS, CLIP, SENSOR, ETC TO REPAIR RHR OUTER FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				1200.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (RHR OUTER FENDER, RH BUMPER MOULDING)				840.00
X KS 86682 HB 400 RH MOULDING ASSY-RR	1.00	152.00	0.00	152.00
X KS 86610 HB 410 LWR COVER-RR BUMPER	1.00	366.00	0.00	366.00
X KS 86614 HB 400 RH BRACKET ASSY-RR B	1.00	27.00	0.00	27.00
X KS 87742 HB 400 RH GARNISH-QTR SIDE	1.00	50.00	0.00	50.00
X KS 86822 HB 400 RH GUARD ASSY-REAR W	1.00	52.00	0.00	52.00
X KS 06032 50 037A FASTERNER-SPLASH SHI	10.00	2.00	0.00	20.00
M KS 06032 50 037A FASTERNER- BUMPER	10.00	2.00	0.00	20.00
Z NOTES ACCIDENT ON 27/09/2020 ALONG TAMPINES AVENUE 10 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP#: GBH5862E TP INS: CHINA TAIPING				
Z NOTES FINALIZATION (3 WORKING DAYS) ATTENTION TO: MR. MARCUS CHUA				

Confirm & accepted by

Parts	687.00
Labour	0.00
Standard Menu	0.00
Specialist Job	2,370.00
Others (Lub, etc)	0.00
Sundry	0.00
Total (w/o GST)	3,057.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.