Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20010410/AES3Q2

JN1SC2F24Z0800736

Date: 16/04/2021

Chassis No:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 2100470123 Policy No: Claimant **GBB3663H** Insured Vehicle No: SLD2937X Vehicle No:

Date of Loss: ΤP 24/09/2020 Nature of Claim: Claim No: 7075247010SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBB3663H Reg No:

NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Make & Model: Engine No: ZD30211841K

Turbo (A)

Reg. Date: 19/01/2009 (Man. Year: 2008) Colour: Gold Odometer: 220451 km

Engine Capacity: 2953 cc

Market Value/New Car N/A Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70 R15C Rear Tyre Size: 165 R13C Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm Front Right Side: Rear Right Side: Toyo 6 mm Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,336.08	4,731.01	4,605.07	49.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	1,870.00	960.00	33.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,166.08	6,601.01	5,565.07	45.74
Approved Total (Overridden) (S\$)		5,250.00		
(S\$)	12,166.08	5,250.00	6,916.08	56.85
+ GST 7.00/7.00% (S\$)	851.63	367.50	484.13	56.85
Nett Amount (S\$)	13,017.71	5,617.50	7,400.21	56.85
+ Car Rental (8.0 x S\$10	00.00/day) (S\$)	800.00		
+ Ot	her Costs (S\$)	100.00		
Ne	tt Liability (S\$)	6,517.50		
Global Sum S	settlement (S\$)	6,510.00		

INSPECTION

Date of Assignment: 28/09/2020

Date Inspected: 28/09/2020 Inspected At: J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578

Singapore 539186

Estimated Period of Repair: 6.0 days Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

1 1 2 2 2 3 1 1 1 1 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 1 1 1 1 1 1		*FRT LH DOOR *FRT LH DOOR HINGES *FRT LH DOOR SIGNAL LAMP *FRT LH DOOR LOCK *FRT LH DOOR AIR DUCT	Dented Bent Cut Not Necessary	1,396.50 FN 112.20 FN 66.00 FN	*1,396.50 FN *112.20 FN *66.00 FN		
3 1 4 1 5 1 6 1 7 1 8 1 9 1 10 1 11 1 11 1 113 1 14 1 15 8 16 1	1 1 1 1 1		*FRT LH DOOR SIGNAL LAMP *FRT LH DOOR LOCK	Cut	66.00 FN			
14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1		*FRT LH DOOR LOCK	-		*66 00 EN		
5 1 6 1 7 1 8 1 9 1 10 1 11 1 12 1 13 1 14 1 15 8 16 1	1 1 1 1			Not Necessary		00.00 FIN		
6 1 7 1 8 1 9 1 10 1 11 1 11 1 13 1 14 1 15 8 16 1	1 1 1		*FRT LH DOOR AIR DUCT		163.90 FN	*- FN		
7 1 3 1 9 1 10 1 11 1 12 1 13 1 14 1 15 8 16 1	1			Not Necessary	56.00 FN	*- FN		
3 1 9 1 10 1 11 1 11 1 12 1 113 1 114 1 115 8 116 1	1		*FRT LH DOOR OUTER MOULDING	Not Necessary	136.20 FN	*- FN		
9 1 10 1 11 1 12 1 13 1 14 1 15 8 16 1	-		*FRT LH DOOR RUBBER	Not Necessary	111.00 FN	*- FN		
10 1 11 1 12 1 13 1 14 1 15 8 16 1			*FRT LH DOOR W/STRIP	Not Necessary	137.40 FN	*- FN		
11 1 12 1 13 1 14 1 15 8 16 1	1		*FRT LH DOOR TRIMBOARD	Cracked	722.50 FN	*722.50 FN		
12 1 13 1 14 1 15 8 16 1	1		*FRT LH CORNER PANEL	Dented	676.60 FN	*389.90 FN		
13 1 14 1 15 8 16 1	1		*LH HEADLAMP	Cracked	473.40 FN	*473.40 FN		
14 1 15 8 16 1	1		*LH HEADLAMP LOWER PANEL	Cracked	98.00 FN	*98.00 FN		
15 8 16 1	1		*FRT BUMPER	Deformed	1,039.50 FN	*903.60 FN		
16 1	1		*FRT BUMPER LH BRACKET	Bent	178.40 FN	*178.40 FN		
	8		*FRT BUMPER CLIPS	Not Necessary	40.80 FN	*- FN		
17 1	1		*FRT LH DOOR PILLAR W/STEP PANEL	Repair	1,646.40 FN	*- FN		
17 1	1		*FRT LH STEP GARNISH	Cracked	139.40 FN	*139.40 FN		
18 1	1		*AIR CON CONDENSER	Not Necessary	792.20 FS	*-FS		
19 1	1		*AIR CON AUTO FAN	Cracked	474.10 FS	*474.10 FS		
20 1	1		*FRT LH TYRE	Not Necessary	200.00 FS	*-FS		
21 1	1		*FRT LH RIM	Cut	339.00 FS	*200.00 FS		
22 1	1		*FRT LH KNUCKLE ARM	Not Necessary	857.80 FS	*-FS		
23 1	1		*FRT LH KNUCKLE BEARING	Not Necessary	173.20 FS	*-FS		
24 1	1		*BODY STICKER	Necessary	25.00 FS	*25.00 FS		
==Francl	chise	part. S=Spcl	Nett. N=NettItemDisc.	_				
				Sub Total (S\$)	10,055.50	5,179.00		
	- Nett Item Discount on N Items 10.00/10.00% (S\$) 719.42 447.99							
				Total Parts (S\$)	9,336.08	4,731.01		
_			Report was unsubmitted during					

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 16/4/2021

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING	New	50.00	0.00
2	PANEL BEATING	New	1,200.00	800.00
3	SPRAY PAINTING	New	1,200.00	800.00
4	WIRING	New	30.00	30.00
5	TOP UP GAS	New	120.00	80.00
6	TRANSFER DOOR PARTS	New	80.00	80.00
7	REMOVE UPHOLSTERY	New	150.00	80.00
		Gross Labour Cost (S\$)	2,830.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >