Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010419/ATF3Q2

Date: 08/01/2021

Odometer:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00028772000

Claimant Vehicle No:

SMH4880D

Insured Vehicle No:

GBB3333K

Date of Loss: 26/09/2020 Nature of TP Claim:

Claim No:

SNM20D203573/C02

G4FC9U753035

167685 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMH4880D Reg No:

Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No:

Reg. Date: 04/11/2009 (Man. Year: 2009) Chassis No: KMHDU41BMAU900907

Colour: Grey

Engine Capacity: 1591 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,682.88	4,086.40	596.48	12.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,740.00	1,240.00	41.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,662.88	5,826.40	1,836.48	23.97
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	7,662.88	4,500.00	3,162.88	41.28
+ GST 7.00/7.00% (S\$)	536.40	315.00	221.40	41.28
Nett Amount (S\$)	8.199.28	4.815.00	3.384.28	41.28

INSPECTION

Date of Assignment: 29/09/2020

Date Inspected: 29/09/2020 Inspected At: N-51 Automotive Pte Ltd (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI

BUKIT AUTOHUB Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2021)		
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SMH4880D)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

INO.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	985.00 FL	*985.00 FL
2	1		*REAR BOOTLID AVANTE EMBLEM	Necessary	41.00 FL	*41.00 FL
3	1		*REAR BOOTLID H LOGO EMBLEM	Necessary	25.00 FL	*25.00 FL
4	1		*REAR BOOTLID S EMBLEM	Necessary	25.00 FL	*25.00 FL
5	1		*REAR BOOTLID MECHANISM LOCK	Damaged	119.50 FL	*119.50 FL
6	1		*REAR BOOTLID MECHANISM LOCK STRIKER	Not Necessary	35.00 FL	*- FL
7	2		*REAR BOOTLID RUBBER GUIDE STOPPER L/R	Not Necessary	44.00 FL	*- FL
8	1		*REAR BOOTLID WEATHER STRIP	Cut	83.40 FL	*83.40 FL
9	1		*REAR BUMPER	Distorted	447.00 FL	*447.00 FL
10	5		*REAR BUMPER INNER BRACKET	Damaged	135.00 FL	*135.00 FL
11	1		*REAR BUMPER INNER SPONGE	Cracked	129.00 FL	*129.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Cracked	285.00 FL	*285.00 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKET L/R	Dented	158.00 FL	*158.00 FL
14	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	68.00 FL	*68.00 FL
15	1		*REAR END PANEL	Dented	581.00 FL	*581.00 FL
16	1		*REAR END PANEL INNER TOP GARNISH	Deformed	64.70 FL	*64.70 FL
17	1		*REAR EXHAUST GASKET	Not Necessary	20.60 FL	*- FL
18	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	58.00 FL	*-FL
19	1		*REAR EXHAUST SILENCER BOX	Bent	711.00 FL	*511.00 FL
20	1		*REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	O/s Torn	326.00 FL	*163.00 FL
21	1		*REAR SPARE TYRE INNER TOP UPHOLSTERY TRIM BOARD COVER	Deformed	249.00 FL	*249.00 FL
22	2		*REAR TAILLAMP BACK RUBBER GASKET L/R	Necessary	37.00 FL	*37.00 FL
23	2		*REAR TAILLAMP L/R	Cracked	626.40 FL	*626.40 FL
24	1		*SET REAR BOOTLID OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*-FS
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
27	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
28	2		*SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R	Necessary	60.00 FS	*30.00 FS
			*SET REAR TAILLAMP CLIPS L/R	Necessary	60.00 FS	*30.00 FS
29	2					
		part. S=S	SpcNett. L=ListItemDisc.	•		
		part. S=S	SpcNett. L=ListItemDisc.	Sub Total (S\$)		5,033.00
		part. S=S				5,033.00 946.60

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR	New G	80.00	80.00
2	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	120.00	60.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,300.00	700.00
4	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	80.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RECONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
7	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	60.00
	Gross Labour Cost (S\$)		2,980.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >