



CLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHUA DONG YANG Reg No/Reg Date SMD8103J / 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003163 Engine No 3A92UHG6508 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/09/2020/ 16:44	BLC	442 / CocoLu	57828			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT AIRDAM, BONNET, FRT SUPPORT PANEL, FRT FENDER RH, SIDE SKIRT RH, FRT WHEEL HOUSING RH, REPAIR FRT FENDER LH, FRT DOOR RH, ROCKER PANEL RH, A-PILLAR RH					6450	X6	5	2250
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								100.00
E PNT88000 REMOVE & INSTALL FRT AIRDAM & SIDE AIRDAM								120.00
M SUNDRY TOP UP AIRCON GAS								80.00
E PNT88000 REMOVE & INSTALL FRT WINDSCREEN (ph 10)								240.00
M SUNDRY APPLY SEALANT FOR FRT WINDSCREEN								80.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT AIRDAM, FRT SUPPORT PANEL, BONNET FRT FENDER RH & LH, FRT DOOR RH, SIDE STILL RH, A-PILLAR RH, ROCKER PANEL RH, WHEEL HOUSING RH,					350	X10		4200.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
B WHEEL ALIGNMENT To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY TRANSFER FRT RIM TO TYRE								30.00
A 54900099 REMOVE & INSTALL DASHBOARD TO FACILITATE REPAIR					7450			675.00
A 54900099 REMOVE & INSTALL ENGINE TO FACILITATE REPAIR pho?					450			675.00
A 54900099 RENEW FRT UNDER CARRIAGE					225			450.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

C/No:

WBA8A12080A022452



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHUA DONG YANG Reg No/Reg Date SMD8103J / 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003163 Engine No 3A92UHG6508 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/09/2020/ 16:44	BLC	442 / CocoLu	57828			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								250 360.00
SUPPLY FRT TYRE								40.00
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION								
M	WHEELHOUSE,FR INR RH	bu			1.00	347.00	23.00	267.19
M	FACE,FR BUMPER	bu			1.00	703.00	23.00	541.31
M	MARK,THREE-DIA	X			1.00	69.00	23.00	53.13
M	COVER,HEADLAMP SUPT PANEL	edw?			1.00	62.00	23.00	47.74
M	GRILLE,FR UNDER	ca			1.00	165.00	23.00	127.05
M	GARNISH,FR BUMPER,RH	ms			1.00	127.00	23.00	97.79
M	AIR DAM,SIDE,FR RH	?			1.00	18.00	23.00	13.86
M	BRACKET,FR BUMPER,RH	?			1.00	13.00	23.00	10.01
M	GRILLE,RADIATOR	X			1.00	554.00	23.00	426.58
M	LATCH,HOOD	X			1.00	69.00	23.00	53.13
M	HOOD	H			1.00	734.00	23.00	565.18
M	HINGE,HOOD,RH	?			1.00	56.00	23.00	43.12
M	INSULATOR,HOOD	ca			1.00	177.00	23.00	136.29
M	FENDER,FR RH	bu			1.00	497.00	23.00	382.69
M	SHIELD,FR WHEELHOUSE,RH	de			1.00	98.00	23.00	75.46
M	PANEL,HEADLAMP SUPPORT,UPR	H X			1.00	65.00	23.00	50.05
M	PANEL ASSY,FR END	report			1.00	1055.00	23.00	812.35
M	PANEL,AIR GUIDE,RH	?			1.00	11.00	23.00	8.47
M	COVER,ENG ROOM UNDER,FR	?			1.00	99.00	23.00	76.23
M	CLIP,HOOD LOCKING	?			1.00	3.00	23.00	2.31
M	MOULDING,WINDSHIELD	?			1.00	100.00	23.00	77.00
M	STOPPER,WINDSHIELD GLASS	?			2.00	3.00	23.00	4.62
M	SPACER,WINDSHIELD	?			2.00	6.00	23.00	9.24
M	SPACER,QTR WINDOW	?			3.00	8.00	23.00	18.48
M	GARNISH,FR DECK	?			1.00	178.00	23.00	137.06
M	GARNISH,FR PILLAR,RH	?			1.00	30.00	23.00	23.10
M	GARNISH,FR FENDER	?			1.00	65.00	23.00	50.05
M	BODY KIT ATTRAGE, TITANLUM GREY,U17	ca			1.00	1643.00	20.00	1314.40
M	HEADLAMP ASSY,RH	ca			1.00	660.00	23.00	508.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Excess:

Steering: Good / Fair / Poor / Burnt



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHUA DONG YANG Reg No/Reg Date SMD8103J / 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003163 Engine No 3A92UH6508 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/09/2020/ 16:44	BLC	442 / CocoLu	57828

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M HEADLAMP ASSY, LH	1.00	660.00	23.00	508.20
M LAMP ASSY, FOG, FR LH	1.00	303.00	23.00	233.31
M TANK, WINDSHIELD WASHER	1.00	74.00	23.00	56.98
M MOTOR, WINDSHIELD WASHER	1.00	30.00	23.00	23.10
M HUB ASSY, FR WHEEL	1.00	215.00	23.00	165.55
M BEARING, FR WHEEL HUB	1.00	121.00	23.00	93.17
M ARM ASSY, FR SUSP, LWR RH	1.00	337.00	23.00	259.49
M STRUT, FR SUSP	1.00	373.00	23.00	287.21
M BEARING, FR SUSP STRUT	1.00	9.00	23.00	6.93
M WHEEL, DISC	1.00	687.00	23.00	528.99

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rasul - Hp 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 28/09/2020 @ 1710

REMARKS: 9 days

REPAIR / EXCESS: TBA

Pay before paint

Confirm & accepted by

7% GST on	Nett	21,175.02
		1482.25

Total Payable	22,657.27
---------------	-----------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.