

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010422/DTD3Q2

Date: 16/10/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30480019011

Claimant Vehicle No : SKP9301H **Insured Vehicle No :** SMA5281M

Date of Loss: 26/09/2020 Nature of Claim: TP Claim No: SNM20D203576/C01/CHUAKK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP9301H**
 Make & Model: MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) Engine No: PE20569096
 Reg. Date: 21/10/2014 (Man. Year: 2014) Chassis No: JM6GJ1071F0145167
 Colour: Red Odometer: 81931 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
 Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm
 Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,920.58	9,363.46	9,557.12	50.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	1,940.00	3,540.00	64.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,400.58	11,303.46	13,097.12	53.68
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	24,400.58	9,000.00	15,400.58	63.12
+ GST 7.00/7.00% (S\$)	1,708.04	630.00	1,078.04	63.12
Nett Amount (S\$)	26,108.62	9,630.00	16,478.62	63.12

INSPECTION

Date of Assignment: 30/09/2020

Date Inspected: 30/09/2020 Inspected At:

JWG INTERNATIONAL PTE LTD
 10 ANG MO KIO INDUSTRIAL PARK
 2A #03-08
 AMK AUTOPOINT SINGAPORE
 568047

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2020)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP9301H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,396.00 FL	*1,151.30 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
3	1		*FRONT BUMPER SIDE RETAINER LH /RH	O/S Bent / N/S Not Necessary	156.00 FL	*17.70 FL
4	1		*FRONT BUMPER SENSORS WIRE HARNESS ASSY	Torn	296.00 FL	*296.00 FL
5	1		*FRONT BUMPER FOGLAMP ASSY	Not fitted	663.00 FL	*- FL
6	1		*FRONT BUMPER FOGLAMP COVER	Dislodged	77.00 FL	*77.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	278.00 FL	*- FL
8	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	20.00 FL	*- FL
9	1		*FRONT RH FENDER	Buckled	658.00 FL	*383.70 FL
10	1		*FRONT RH FENDER SHIELD	Torn	115.00 FL	*115.00 FL
11	1		*SET FRONT RH FENDER SHIELD CLIPS	Necessary	18.00 FL	*18.00 FL
12	1		*FRONT HEADLAMP RH	Broken	2,378.00 FL	*2,378.00 FL
13	1		*FRONT HEADLAMP RH BRACKET	Not Necessary	98.00 FL	*- FL
14	1		*FRONT RH ABSORBER	Distorted	460.00 FL	*460.00 FL
15	1		*FRONT RH ABSORBER MOUNTING	Not Necessary	95.00 FL	*- FL
16	1		*FRONT RH ABSORBER DUST COVER	Not Necessary	49.00 FL	*- FL
17	1		*FRONT RH ABSORBER STOPPER	Not Necessary	46.00 FL	*- FL
18	1		*FRONT RH TIE ROD	Not Necessary	238.00 FL	*- FL
19	1		*FRONT RH TIE ROD END	Not Necessary	249.00 FL	*- FL
20	1		*FRONT RH STEERING RACK ASSY	Not Necessary	1,161.00 FL	*- FL
21	1		*FRONT STABILIZER BAR	Not Necessary	422.00 FL	*- FL
22	1		*FRONT RH STABILIZER LINK	Not Necessary	116.00 FL	*- FL
23	1		*FRONT RH KNUCKLE ARM	Distorted	502.00 FL	*387.70 FL
24	1		*FRONT RH LOWER ARM	Distorted	554.00 FL	*246.00 FL
25	1		*FRONT RH WHEEL BEARING & HUB ASSY	Damaged	668.00 FL	*539.70 FL
26	1		*FRONT RH DRIVE SHAFT ASSY	Not Necessary	1,897.00 FL	*- FL
27	1		*FRONT RH SIDE MIRROR	Not Necessary	787.00 FL	*- FL
28	1		*FRONT SUPPORT PANEL	Cracked	1,096.00 FL	*699.00 FL
29	1		*FRONT REINFORCEMENT BAR	Bent	613.00 FL	*613.00 FL
30	1		*FRONT REINFORCEMENT SPONGE	Not Necessary	329.00 FL	*- FL
31	1		*FRONT GRILLE	Mtg Broken	517.00 FL	*517.00 FL
32	1		*SET FRONT GRILLE CLIPS	Necessary	25.00 FL	*25.00 FL
33	1		*FRONT GRILLE CHROME	Cut	319.00 FL	*319.00 FL
34	1		*FRONT GRILLE INNER LOWER GARNISH	Not Necessary	179.00 FL	*- FL
35	1		*FRONT WASHER TANK	Broken	378.00 FL	*188.50 FL
36	1		*FRONT WASHER TANK MOTOR	Damaged	298.00 FL	*159.00 FL
37	1		*FRONT WASHER TANK FILLER PIPE	Not Necessary	109.00 FL	*- FL
38	1		*FRONT WASHER TANK FILLER PIPE BRACKET	Not Necessary	67.00 FL	*- FL
39	1		*FRONT ENGINE UNDER COVER	Cracked	274.00 FL	*274.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT ENGINE UNDER COVER CLIPS	Necessary	20.00 FL	*20.00 FL
41	1		*FRONT BONNET	Dented	1,723.00 FL	*1,204.00 FL
42	2		*FRONT BONNET HINGE LH /RH	Not Necessary	216.00 FL	*- FL
43	1		*FRONT FENDER BRACKET RH	Bent	422.98 FL	*422.98 FL
44	1		*FRONT ENGINE UNDERCOVER LOWER	Deformed	257.75 FL	*257.75 FL
45	1		*FRONT RH TYRE	Not Necessary	400.00 FS	*- FS
46	1		*SET FRONT SENSORS	Damaged	500.00 FS	*220.00 FS
47	1		*FRONT RH BRANDED SPORTS RIM	Cut	1,800.00 FS	*500.00 FS
					Sub Total (S\$)	22,975.73 11,524.33
					- List Item Discount on L Items 20.00/20.00% (S\$)	4,055.15 2,160.87
					Total Parts (S\$)	18,920.58 9,363.46

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT RH DAMAGED UNDER CARRIAGE PARTS	New	500.00	150.00
2	TO CONDUCT COMPUTERIZE 4-WHEELED ALIGNMENT TEST	New	180.00	60.00
3	TO ROTATE & BALANCE FRONT RH TYRE	New	100.00	20.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,800.00	800.00
5	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	New	1,800.00	800.00
6	TO REFIT NEW FRONT BUMPER SENSORS ON NEW FRONT BUMPER	New	180.00	40.00
7	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
8	TO COMPUTERIZED REFOCUS FRONT HEADLAMP BEAM	New	120.00	0.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
10	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	New	300.00	40.00
Gross Labour Cost (\$\$)			5,480.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >