

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20010430/QPA3Q2

**Date:** 12/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900252127

**Claimant**  
**Vehicle No :** SHB5329P **Insured Vehicle No :** SMQ8280L

Date of Loss: 23/09/2020 Nature of Claim: TP Claim No: 6305957708SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB5329P</b>	Engine No:	2ZRS099852
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU603573255
Reg. Date:	01/11/2017 (Man. Year: 2017)	Odometer:	262412 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,963.54	6,952.13	13,011.41	65.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,841.00	1,070.00	3,771.00	77.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>24,804.54</b>	<b>8,022.13</b>	<b>16,782.41</b>	<b>67.66</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,650.00</b>		
<b>Nett Amount (\$\$)</b>	<b>24,804.54</b>	<b>6,650.00</b>	<b>18,154.54</b>	<b>73.19</b>
<b>+ Loss of Use (7.0 x S\$50.00/day) (\$\$)</b>		350.00		
<b>+ Car Rental (7.0 x S\$108.07/day) (\$\$)</b>		756.49		
<b>+ Doc/Search Fee (\$\$)</b>		7.00		
<b>Nett Liability (\$\$)</b>		<b>7,763.49</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>7,760.00</b>		

### INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 24/09/2020 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 5.0 days

---

**Adjuster:** OI SUN PIN**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FR BUMPER (DISC 25%)	Crumpled	495.50 F	*371.63 F
2	1		*SUPPORT ,FR BUMPER LH (DISC 25%)	Crumpled	82.30 F	*61.73 F
3	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	87.10 F	*65.33 F
4	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
5	1		*UNIT HEADLAMP LH (DISC 25%)	Scratched	2,558.90 F	*1,919.18 F
6	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
7	1		*LINER ,FR FENDER LH (DISC 25%)	Crumpled	194.30 F	*145.73 F
8	1		*WHEEL DISC FRONT (DISC 25%)	Cut	1,555.10 F	*1,166.33 F
9	1		*COVER ,ENGINE UNDER SIDE LH (DISC 25%)	Crumpled	76.90 F	*57.68 F
10	1		*SUPPORT SUB-ASSY ,FRONT SUSPENSION RH & (DISC 25%)	Crumpled	198.40 F	*148.80 F
11	1		*ABSORBER SET ,SHOCK FRONT LH (DISC 25%)	Bent	398.10 F	*298.58 F
12	1		*KNUCKLE STEERING LH (DISC 25%)	Bent	555.20 F	*416.40 F
13	1		*LOWER ARM SUB -ASSY ,FRONT LH (DISC 25%)	Bent	631.60 F	*473.70 F
14	1		*HUB & BEARING ASSY ,RH & LH (DISC 25%) (2 PCS)	Jammed	554.20 F	*415.65 F
15	1		*END SET ,TIE ROD LH (DISC 25%)	Bent	155.90 F	*116.93 F
16	1		*LINK ASSY ,FRONT STABILIZER ,RH & LH (DISC 25%) (2 PCS)	Bent	196.70 F	*147.53 F
17	1		*JOINT ASSY ,LWR BALL ,RH & LH (DISC 25%) (2 PCS)	Bent	200.10 F	*150.08 F
18	1		*LAMP ASSY ,FOG LH (DISC 10%)	Crumpled	910.20 F	*819.18 F
19	1		*TYRE (SN)	Cut	126.74 F	*126.74 F
20	1		*GRILLE ,RADIATOR	Serviceable	165.00 F	*- F
21	1		*GRILLE SUB -ASSY	Serviceable	335.60 F	*- F
22	1		*COMPUTER SUB-ASSY HEADLAMP ,LH NO.1	Serviceable	486.40 F	*- F
23	1		*HOOD SUB-ASSY	Serviceable	938.40 F	*- F
24	1		*HINGE ASSY ,HOOD ,LH	Serviceable	57.00 F	*- F
25	1		*PAD ,FR WHEEL LH	Serviceable	57.70 F	*- F
26	1		*RETAINER ,FR FENDER NO 2	Serviceable	16.80 F	*- F
27	1		*RETAINER ,FR FENDER NO 1	Serviceable	4.90 F	*- F
28	1		*CLIP ,PIN HOLD	Serviceable	1.40 F	*- F
29	1		*BRACE SUB-ASSY ,FENDER APRON LH	Serviceable	282.70 F	*- F
30	1		*APRON ASSY ,FRONT FENDER LH	Serviceable	171.20 F	*- F
31	1		*SUPPORT ,RADIATOR UPPER LH	Serviceable	76.70 F	*- F
32	1		*COVER ENGINE UNDER SIDE LH	Serviceable	76.90 F	*- F
33	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Serviceable	576.00 F	*- F
34	1		*ABSORBER SET ,SHOCK ,FRONT LH	Serviceable	398.10 F	*- F
35	1		*SUPPORT SUB-ASSY FRONT SUSPENSION ,RH &	Serviceable	198.40 F	*- F
36	1		*SEAT SUB-ASSY ,FRONT SPRING ,W/INSULATOR RH	Serviceable	38.20 F	*- F
37	2		*BUMPER FRONT SPRING RH& LH	Serviceable	14.50 F	*- F
38	2		*SPRING FRONT COIL RH & LH	Serviceable	160.60 F	*- F
39	2		*INSULATOR FRONT COIL SPRING ,LOWER RH & LH	Serviceable	28.10 F	*- F
40	2		*LINK ASSY FRONT STABILIZER RH & LH	Serviceable	196.70 F	*- F
41	2		*BRACKET FRONT STABILIZER NO 1 RH & LH	Serviceable	45.90 F	*- F
42	1		*COVER DISC BRAKE DUST FRONT LH	Serviceable	48.00 F	*- F
43	1		*PAD KIT DISC BRAKE FRONT	Serviceable	228.70 F	*- F
44	1		*SHAFT ASSY ,FRONT DRIVE LH	Serviceable	1,175.10 F	*- F
45	1		*SENSOR SPEED FRONT LH	Serviceable	450.50 F	*- F
46	1		*PAND SUB ASSY ,FRONT DOOR LH	Serviceable	1,249.60 F	*- F
47	1		*STICKER DECAL SMRT (DOOR)	Serviceable	60.00 F	*- F
48	1		*MIRROR ASSY ,OUTER REAR VIEW ,LH	Serviceable	1,283.90 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*COVER OUTER MIRROR LH	Serviceable	89.50 F	*- F
50	1		*MIRROR OUTER GLASS LH	Serviceable	143.10 F	*- F
51	1		*LAMP ASSY SIDE MIRROR TURN SIGNAL LH	Serviceable	162.20 F	*- F
52	1		*COVER ENGINE UNDER SIDE RH	Serviceable	76.90 F	*- F
53	1		*COVER ASSY ,ENGINE	Serviceable	180.10 F	*- F
54	1		*COVER ASSY ,ENGINE UNDER CENTER SET	Serviceable	452.80 F	*- F
55	1		*PAD FR WHEEL LH	Serviceable	57.70 F	*- F
56	1		*FENDER SUB-ASSY ,FR LH	Repair	933.10 F	*- F

F=Franchise part.

**Total Parts (S\$) 19,963.54 6,952.13**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	1,183.00	400.00
2	SPRAY PAINT	New	2,232.00	400.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREAS	New	100.00	30.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
6	TO REMOVE AND REFIT FRT UNDER CARRIAGE	New	200.00	100.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
8	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	0.00
9	TO REMOVE AND REFIT TYRE	New	120.00	20.00
10	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
11	TO REPLACE SUNDRY PARTS	New	100.00	0.00
12	TO WASH AND VACUUM	New	60.00	0.00
13	TOWING CHARGE	New	56.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,841.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >