12/16/21, 3:40 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010432/ARA3Q2

Date: 16/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900232928

Claimant Vehicle No: SFL3328B Insured Vehicle No: SMP9347C

Date of Loss: 26/09/2020 Nature of Claim: TP Claim No: 0783433040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFL3328B

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN014938

Reg. Date: 24/08/2016 (Man. Year: 2016) Chassis No: WAUZZZF48GA111604

Colour: Grey Odometer: 59886 km

Engine Capacity: 1395 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
14,444.00	3,197.36	11,246.64	77.86
0.00	0.00	0.00	
2,772.00	1,242.00	1,530.00	55.19
0.00	0.00	0.00	
0.00	0.00	0.00	
17,216.00	4,439.36	12,776.64	74.21
1,205.12	310.76	894.36	74.21
18,421.12	4,750.12	13,671.00	74.21
x S\$60.00/day) (S\$)	180.00		
oc/Search Fee (S\$)	2.00		
	14,444.00 0.00 2,772.00 0.00 0.00 17,216.00 1,205.12	14,444.00 3,197.36 0.00 0.00 2,772.00 1,242.00 0.00 0.00 0.00 0.00 17,216.00 4,439.36 1,205.12 310.76 18,421.12 4,750.12 x \$\$60.00/day) (\$\$) 180.00	14,444.00 3,197.36 11,246.64 0.00 0.00 0.00 2,772.00 1,242.00 1,530.00 0.00 0.00 0.00 0.00 0.00 0.00 17,216.00 4,439.36 12,776.64 1,205.12 310.76 894.36 18,421.12 4,750.12 13,671.00 x \$\$60.00/day) (\$\$)

Nett Liability (S\$)

INSPECTION

Date of Assignment: 30/09/2020

Premium Automobiles Pte Ltd (UBI)

4,932.12

Date Inspected: 30/09/2020 Inspected At: 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	282.00 FS	*-FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	194.00 FS	*-FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	208.00 FS	*-FS
6	1		*RADIATOR GRILLE	Cracked	1,799.00 FS	*1,439.20 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	361.00 FS	*-FS
8	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*-FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
10	1		*FRONT BUMPER TOP COVER	Not Necessary	126.00 FS	*-FS
11	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
12	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
13	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*- FS
14	2		*LOCK CARRIER BRACKET SUPPORT-LH/RH	Not Necessary	56.00 FS	*- FS
15	1		*LED HEADLIGHT -LH	Not Necessary	7,693.00 FS	*- FS
16	1		*LIFT CYLINDER -LH	Not Necessary	208.00 FS	*- FS
17	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
18	1		*SUNDRIES	Necessary	200.00 FS	*9.36 FS
⊢=⊢ra	anchise	part. S=Spc	Nett.	Total Parts (S\$)	14.444.00	3,197.36
				111111111111111111111111111111111111111		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPEATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORHANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	Γ New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$		2,772.00	1,242.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >