

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/MSG20010433/UVF3Q2

**Date:** 28/10/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29146062

**Claimant**  
**Vehicle No :** SMA5868X

**Insured Vehicle No :** YP3938U

Date of Loss: 28/09/2020

Nature of Claim: TP

Claim No: 629272

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA5868X**

Make & Model: VOLVO XC60, 2.0 T5 (A)

Engine No: B4204T111078159

Reg. Date: 31/10/2014 (Man. Year: 2014)

Chassis No: YV1DZ40LDF2654994

Colour: Silver

Odometer: 125647 km

Engine Capacity: 1969 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/60 R18

Rear Tyre Size:

235/60 R18

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

*The above values represent the remaining tyre treads depth*

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	51,936.00	22,180.34	29,755.66	57.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,890.00	3,400.00	3,490.00	50.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>58,826.00</b>	<b>25,580.34</b>	<b>33,245.66</b>	<b>56.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>17,500.00</b>		
<b>(S\$)</b>	58,826.00	17,500.00	41,326.00	70.25
<b>+ GST 7.00/7.00% (S\$)</b>	4,117.82	1,225.00	2,892.82	70.25
<b>Nett Amount (S\$)</b>	<b>62,943.82</b>	<b>18,725.00</b>	<b>44,218.82</b>	<b>70.25</b>

### INSPECTION

Date of Assignment: 30/09/2020

Date Inspected: 29/09/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair: 9.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2020)
<b>Parts:</b>	M1-SUV	VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMA5868X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	2,050.00 F	*1,856.69 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	180.00 F	*150.48 FL
3	1		*TAILGATE	Warped/Cracked	3,800.00 F	*3,239.54 FL
4	1		*TAILGATE VOLVO EMBLEM	Necessary	105.00 F	*98.00 FL
5	1		*TAILGATE TS EMBLEM	Necessary	155.00 F	*85.00 FL
6	1		*TAILGATE XC 60 EMBLEM	Necessary	680.00 F	*90.00 FL
7	1		*TAILGATE INNER LOCK	Jammed	920.00 F	*650.00 FL
8	1		*TAILGATE REAR WIPER MOTOR	Cracked / Jammed	950.00 F	*688.00 FL
9	1		*TAILGATE REAR WIPER	Serviceable	288.00 F	*- FL
10	1		*TAILGATE REAR WIPER BLADE	Not Necessary	100.00 F	*- FL
11	1		*TAILGATE INNER LOCK CONTROL UNIT	Cracked / Shorted	605.00 F	*485.00 FL
12	1		*TAILGATE WEATHERSTRIP	Not Necessary	399.00 F	*- FL
13	1		*TAILGATE OUTER CHROME MOULDING	Cracked	380.00 F	*247.77 FL
14	1		*TAILGATE INNER TRIM	Deformed / Cracked	1,050.00 F	*750.00 FL
15	1		*REAR BUMPER TOP	Distorted	2,500.00 F	*2,318.96 FL
16	1		*REAR BUMPER BOTTOM	Distorted	1,200.00 F	*658.68 FL
17	1		*REAR BUMPER LOWER SKIRTING	Distorted	620.00 F	*420.00 FL
18	2		*REAR BUMPER REFLECTORS	Not Necessary	500.00 F	*- FL
19	1		*REAR BUMPER PDC SENSORS (4 PCS)	Shorted (2 PCS ONLY)	1,400.00 F	*640.42 FL
20	1		*REAR BUMPER REINFORCEMENT	Distorted	1,500.00 F	*1,445.45 FL
21	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
22	2		*REAR BUMPER SIDE RETAINERS	Bent / Twisted	500.00 F	*230.00 FL
23	1		*REAR BUMPER INNER PROTECTOR	Distorted	480.00 F	*323.21 FL
24	2		*TAILLAMPS	Cracked	2,400.00 F	*1,960.00 FL
25	1		*REAR END PANEL	Badly Dented	1,150.00 F	*845.00 FL
26	1		*REAR END PANEL TOP GARNISH	Serviceable	485.00 F	*- FL
27	1		*REAR FLOOR PANEL	Repair	2,400.00 F	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	720.00 F	*- FL
29	1		*REAR FENDER	Repair	2,205.00 F	*- FL
30	1		*REAR FENDER INNER TRIM	Not Necessary	688.00 F	*- FL
31	1		*REAR EXHAUST	Repair	1,800.00 F	*- FL
32	1		*REAR EXHAUST HEAT SHIELD	Bent	488.00 F	*315.00 FL
33	1		*REAR EXHAUST CHROMES	N/S Dented	700.00 F	*288.00 FL
34	1		*BONNET	Repair	3,200.00 F	*- FL
35	1		*FRONT BUMPER	Distorted	2,800.00 F	*1,645.32 FL
36	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	699.00 F	*- FL
37	1		*FRONT BUMPER INNER PROTECTOR	Torn	450.00 F	*250.00 FL
38	1		*FRONT BUMPER REINFORCEMENT	Bent	1,500.00 F	*1,399.21 FL
39	1		*FRONT BUMPER SIDE RETAINER N/S	Serviceable	250.00 F	*- FL
40	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
41	1		*FRONT BUMPER LAMP N/S	Cracked	625.00 F	*385.50 FL
42	1		*HEADLAMP N/S	Broken	4,500.00 F	*2,465.32 FL
43	1		*FRONT FENDER N/S	Repair	885.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT NOZZLE COVER N/S	Missing	30.00 F	*30.00 FL
45	1		*FRONT NOZZLE N/S	Cracked	299.00 F	*166.50 FL
46	1		*WIPER WASHER TANK	Deformed	350.00 F	*240.00 FL
47	1		*FRONT SUPPORT PANEL	Repair	1,550.00 F	*- FL
48	1		*REAR LICENCE PLATE	Scratched	50.00 FS	*40.00 FS
49	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
50	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
51	1		*SET REAR FLOOR PANEL INSULATOR	Not fitted	300.00 FS	*- FS
52	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
53	1		*FRONT SPORT RIM N/S	Repair	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** **51,936.00** **24,627.05**  
**- List Item Discount on L Items 0.00/10.00% (\$\$)** **0.00** **2,446.71**

**Total Parts (\$\$)** **51,936.00** **22,180.34**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	100.00	50.00
3	TO DISMANTLE & REPLACED REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	200.00	80.00
6	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
7	TO TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
8	TO REFILL AIR CON GAS	New	120.00	0.00
9	TO SPRAY RUST PROOFING	New	180.00	80.00
10	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	3,000.00	1,200.00
12	TO PUTTY & SPRAY PAINTING	New	2,600.00	1,700.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,890.00</b>	<b>3,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >