

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20010434/QES3Q2**Date:** 05/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994005
<b>Claimant Vehicle No :</b>	SMG4114M	<b>Insured Vehicle No :</b>	YN3397R
Date of Loss:	27/09/2020	Nature of Claim:	TP
		Claim No:	2373922536SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMG4114M</b>		
Make & Model:	RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A)	Engine No:	K9KF649D058949
Reg. Date:	18/12/2018 (Man. Year: 2018)	Chassis No:	VF1RFA00361665861
Colour:	White	Odometer:	145937 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,268.19	1,638.09	4,630.10	73.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	800.00	880.00	52.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,948.19</b>	<b>2,438.09</b>	<b>5,510.10</b>	<b>69.33</b>
<b>+ GST 7.00/7.00% (S\$)</b>	556.37	170.67	385.70	69.32
<b>Nett Amount (S\$)</b>	<b>8,504.56</b>	<b>2,608.76</b>	<b>5,895.80</b>	<b>69.33</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	29/09/2020		
Date Inspected:	29/09/2020	Inspected At:	Munich Autocare Pte Ltd (HQ) 60 Jalan Lam Huat, #07-43 Singapore 737869
Estimated Period of Repair:	3.0 days		

**Adjuster:** OI SUN PIN**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Broken	699.78 FL	*699.78 FL
2	1		*WIPER BLADE	Crumpled	57.00 FL	*57.00 FL
3	1		*TAILLIGHT ,TAILGATE RH	Crumpled	548.88 FL	*548.88 FL
4	1		*BUMPER ,REAR	Repair	1,152.96 FL	*- FL
5	1		*BUMPER BEAM ,REAR	Serviceable	670.65 FL	*- FL
6	1		*TAILGATE COVER	Repair	749.28 FL	*- FL
7	1		*EMBLEM	Necessary	151.20 FL	*97.00 FL
8	1		*LETTERING SCENIC	Necessary	138.10 FL	*86.50 FL
9	1		*LETTERING RENAULT	Necessary	138.10 FL	*86.50 FL
10	1		*TAILGATE ASSY	Serviceable	2,247.60 FL	*- FL
11	1		*TINTED FILM	Necessary	350.00 FS	*200.00 FS
12	1		*PHC DECALS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,923.55	1,795.66
- List Item Discount on L Items 10.00/10.00% (\$\$)	655.36	157.57
Total Parts (\$\$)	6,268.19	1,638.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR REPLACING DAMAGED PARTS AS PER ABOVE	New	1,000.00	400.00
2	TO CHECK TAILGATE WATER SEEPAGE	New	80.00	0.00
3	LABOUR FOR PUTTY AND SPRAY PAINT ON REAR BUMPER AND TAILGATE PANEL	New	600.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>1,680.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >