

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG20010440/KPA3Q2  
**Date:** 29/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800135548
<b>Claimant Vehicle No :</b>	SHD519E	<b>Insured Vehicle No :</b>	SMF5857B
Date of Loss:	24/09/2020	Nature of Claim:	TP
		Claim No:	9894165469SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD519E</b>		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003116
Reg. Date:	17/11/2017 (Man. Year: 2016)	Chassis No:	VF1ABL15AUC283438
Colour:	Metallic White/Red	Odometer:	216230 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Dunlop 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	40,774.79	15,711.06	25,063.73	61.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,310.00	4,770.00	6,540.00	57.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>52,084.79</b>	<b>20,481.06</b>	<b>31,603.73</b>	<b>60.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>16,400.00</b>		

(S\$)	52,084.79	16,400.00	35,684.79	68.51
<b>+ GST 7.00/7.00% (S\$)</b>	3,645.94	1,148.00	2,497.94	68.51
<b>Nett Amount (S\$)</b>	<b>55,730.73</b>	<b>17,548.00</b>	<b>38,182.73</b>	<b>68.51</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 29/09/2020

Date Inspected: 29/09/2020

Estimated Period of Repair: 14.0 days

Inspected At: Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Torn	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Distorted / Dented	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Cracked	82.10 FL	*82.10 FL
5	1		*BUMPER RETAINER RH REAR	Cracked	59.80 FL	*59.80 FL
6	1		*BUMPER REFLECTOR RH	Broken	16.60 FL	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
10	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
11	1		*BUMPER HARNESS REAR	Serviceable	301.10 FL	*- FL
12	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
13	1		*OUTER PANEL REAR (END PANEL)TRIM	Cracked	404.56 FL	*404.56 FL
14	1		*TAILLAMP RH	Broken	401.40 FL	*401.40 FL
15	1		*TAILLAMP PANEL RH	Bent	401.40 FL	*401.40 FL
16	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
17	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
18	1		*BOOT WEATHERSTRIP	Distorted / Cut	178.20 FL	*178.20 FL
19	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	*277.70 FL
20	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
21	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
22	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	*- FL
23	1		*BOOT STRUT	Serviceable	145.10 FL	*- FL
24	1		*BOOT HINGE RH	Repair	254.20 FL	*- FL
25	1		*EXHAUST REAR	Bent	4,737.24 FS	*3,200.00 FS
26	1		*EXHAUST CAP REAR	Bent	125.40 FL	*125.40 FL
27	1		*FENDER PANEL REAR RH	Bent	1,933.20 FL	*1,933.20 FL
28	1		*WHEELARCH REAR RH	Cracked	275.40 FL	*275.40 FL
29	1		*FENDER PANEL INNER TRIM REAR RH	Deformed	671.45 FL	*671.45 FL
30	1		*SPARE WHEEL PANEL	Repair	1,229.40 FL	*- FL
31	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
32	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
33	1		*CHASSIS PANEL REAR RH	Repair	2,192.40 FL	*- FL
34	1		*FENDER PANEL INNER REAR RH	Bent	1,241.60 FL	*1,241.60 FL
35	1		*FENDER INNER BOARD RH	Serviceable	561.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FENDER WHEEL HOUSING PANEL REAR RH	Repair	4,682.09 FL	*- FL
37	1		*KNUCKLE ARM REAR RH	Serviceable	472.10 FL	*- FL
38	1		*WHEEL HUB NUT	Serviceable	41.80 FL	*- FL
39	1		*WHEEL HUB CAP	Serviceable	30.50 FL	*- FL
40	1		*REAR AXLE	Serviceable	3,469.00 FL	*- FL
41	1		*AXLE SPRING ARM RH	Serviceable	220.60 FL	*- FL
42	1		*UPPER CONTROL ARM REAR RH	Serviceable	543.50 FL	*- FL
43	1		*ABSORBER REAR	Serviceable	217.30 FL	*- FL
44	1		*STABILIZER BAR REAR	Serviceable	427.90 FL	*- FL
45	1		*STABILIZER LINK REAR	Serviceable	55.20 FL	*- FL
46	1		*SUBFRAME ARM REAR RH	Serviceable	198.33 FL	*- FL
47	1		*RODE -LONG REAR RH	Serviceable	120.16 FL	*- FL
48	1		*KNUCKLE HUB+BEARING RH	Serviceable	272.30 FL	*- FL
49	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	*- FL
50	1		*DOOR LOCK REAR RH	Repair	467.30 FL	*- FL
51	1		*DOOR FINISHER REAR RH	Serviceable	230.30 FL	*- FL
52	1		*SET PARKING AID	Torn	700.00 FS	*400.00 FS
53	1		*SET REAR BUMPER CLIP	Necessary	90.00 FS	*75.00 FS
54	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	65.00 FS	*- FS
55	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	65.00 FS	*- FS
56	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	60.00 FS	*- FS
57	1		*SET BUMPER LOWER REAR RIVET	Necessary	80.00 FS	*65.00 FS
58	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	90.00 FS	*- FS
59	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
60	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
61	1		*SET BOOT FINISHER CLIP	Not Necessary	60.00 FS	*- FS
62	1		*TAILLAMP CLIP	Necessary	55.00 FS	*15.00 FS
63	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
64	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	130.00 FS	*- FS
65	1		*FENDER INNER TRIM CLIP RH	Not Necessary	65.00 FS	*- FS
66	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	75.00 FS	*- FS
67	2		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
68	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
69	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS
70	2		*SEAM SEALANT	Not Necessary	170.00 FS	*- FS
71	1		*RENAULT TYRE 215/60/16	Serviceable	330.00 FS	*- FS
72	1		*RENAULT TYRE RIM	Dented	380.00 FS	*380.00 FS
73	1		*SET END PANEL TRIM CLIP	Not Necessary	60.00 FS	*- FS
74	1		*BOOT TRIM BOARD CLIP	Not Necessary	60.00 FS	*- FS
75	1		*EXHAUST MOUNTING	Serviceable	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*EXHAUST BRACKET REAR	Repair	55.00 FS	*- FS
77	1		*REAR BOOT STICKER 6555-3333	Not Necessary	100.00 FS	*- FS
78	1		*BUMPER COVER FRT	Cracked	747.20 FL	*747.20 FL
79	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
80	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
81	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
82	1		*BUMPER RETAINER FRT RH	Serviceable	101.40 FL	*- FL
83	1		*RADIATOR GRILLE	Dented	969.90 FL	*969.90 FL
84	1		*RADIATOR GRILLE FRAME	Cracked	686.00 FL	*686.00 FL
85	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
86	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
87	1		*BUMPER CLIP FRT	Necessary	85.00 FS	*66.00 FS
88	1		*BUMPER RETAINER CLIP FRT	Not Necessary	70.00 FS	*- FS
89	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	70.00 FS	*- FS
90	1		*BUMPER FOG LAMP GRILLE CLIP	Not Necessary	65.00 FS	*- FS
91	1		*BUMPER SPOILER CLIP	Not Necessary	65.00 FS	*- FS
92	1		*BUMPER BRACKET CLIP	Not Necessary	75.00 FS	*- FS
93	1		*SET FRONT LICENCE PLATE WIHT HOLDER	Dented	120.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>44,321.19</b>	<b>16,970.51</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	3,546.40	1,259.45
<b>Total Parts (\$\$)</b>	<b>40,774.79</b>	<b>15,711.06</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING FEES	New	150.00	50.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	1,800.00
3	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	20.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
5	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	250.00	80.00
6	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
7	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
8	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	90.00
9	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	120.00
10	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	250.00	0.00
11	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
12	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE AND AXLE ASSY ,REMOVAL AND RENEWAL OF PARTS FINAL CHECKING AND TESTING	New	480.00	0.00
13	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	400.00	250.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
16	TO CHECK ABS AND BRAKE EFFICIENCY,FINAL CHECKING AND TESTING	New	380.00	0.00
17	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	1,320.00
18	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
19	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
20	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	220.00
21	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,200.00	500.00
22	TO REMOVE AND REFIT OF BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,310.00</b>	<b>4,770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

