

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20010443/ADA3Q2

Date: 26/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900015758-01

Claimant
Vehicle No : GX3788G **Insured Vehicle No :** GBJ1911M

Date of Loss: 14/09/2020 Nature of Claim: TP Claim No: 9064459702SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX3788G		
Make & Model:	TOYOTA LITEACE, 2.2 5 DR (A)	Engine No:	3C3991012
Reg. Date:	20/04/2004 (Man. Year: 2004)	Chassis No:	CR425008789
Colour:	Silver	Odometer:	334280 km
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165 R13C	Rear Tyre Size:	165 R13C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,576.80	731.25	845.55	53.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	230.00	570.00	71.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,376.80	961.25	1,415.55	59.56
Approved Total (Overridden) (S\$)		700.00		
(S\$)	2,376.80	700.00	1,676.80	70.55
+ GST 7.00/7.00% (S\$)	166.38	49.00	117.38	70.55
Nett Amount (S\$)	2,543.18	749.00	1,794.18	70.55
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		951.00		

INSPECTION

Date of Assignment: 29/09/2020

Date Inspected: 29/09/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	401.60 F	*401.60 FL
2	8		*FRONT BUMPER CLIP	Necessary	52.00 F	*30.00 FL
3	2		*FRONT R/H BUMPER SIDE RETAINER	Necessary	190.80 F	*70.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	255.40 F	*- FL
5	1		*FRONT BUMPER BEAM	Not Necessary	108.00 F	*- FL
6	1		*FRONT R/H BUMPER VENT	Not Necessary	95.60 F	*- FL
7	1		*FRONT R/H HEAD LAMP HOUSING	Cracked	125.80 F	*125.80 FL
8	1		*FRONT GRILLE	Cracked	347.60 F	*347.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,576.80	975.00
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	243.75
Total Parts (\$)	1,576.80	731.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	100.00	30.00
2	TUFF KOTE	New	150.00	0.00
3	TO REMOVE & REFIT FRONT BUMPER	New	300.00	200.00
4	SPRAY PAINTING	New	250.00	0.00
Gross Labour Cost (\$\$)			800.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >