

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20010447/APA3Q2

Date:

19/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800024901

Claimant Vehicle No : SLN7699Y**Insured Vehicle No :**

SLX365D

Date of Loss: 14/09/2020

Nature of Claim:

TP

Claim No:

2092361750SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLN7699Y**

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No:

CVN034021

Reg. Date: 17/05/2017 (Man. Year: 2017)

Chassis No:

WAUZZZF45HA129155

Colour: White

Odometer:

29495 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size:

225/50 R17

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,973.00	0.00	3,973.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,475.00	1,602.00	4,873.00	75.26
+ GST 7.00/7.00% (S\$)	453.25	112.14	341.11	75.26

Nett Amount (S\$)	6,928.25	1,714.14	5,214.11	75.26
		+ Loss of Use (3.0 x S\$60.00/day) (S\$)	180.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	1,896.14	

INSPECTION

Date of Assignment: 01/10/2020

Date Inspected: 01/10/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,181.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	72.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	220.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	246.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR- LH-RH	Not Necessary	82.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	886.00 FS	*- FS
7	2		*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	44.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR -INNER /OUTER (NPA)	Not Necessary	0.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
					Total Parts (\$\$)	3,973.00
						0.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >