

(08/11/13) wef
ASS. REC. BY: *marcus*

REF: *CC4/EQ120010448/U993*

ASSIGNMENT

From: ☒ Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *GBC5142B*

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: *GBC5142B*

Yr Regn:

14/9, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *SSANGYONG / MUSSO*

c.c *2874*

Colour *3/4ck*

A/C: Insured / Std / NI / NA

Sp. Reading

540659

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KPAWA2EDS6P407128

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *Good* / Jammed / Leaked / Burnt or

Brake: *Good* / Jammed / Leaked / Burnt or

Modi: *6* / S/Rim / STD A/Rim or

Tyre Size: F:

R:

235/70R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

920110

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/9/20

D.O.I.

30/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

we 31-8-2021 30111mth LFA

MV 101000

LFA 4239

NV 95761

7/10/20 L/S 5700 confirmed with wiston

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

) ☐ S + RS, ☐ SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

Vehicle: GBC5142B

Make & Model: Ssangyong Musso

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Front Left Door		body	\$ 1,850.00	✓ 1480.00
2	Front Left Door Proector		DL	\$ 550.00	✓ 450.00
3	Front Left Door Proector Chrome		surf	\$ 180.00	✓
4	290S Wording		net	\$ 80.00	✓ 50.00
5	Rear Left Door		body	\$ 1,650.00	✓ 1350
6	Rear Left Door Proector		DL	\$ 550.00	✓ 420.00
7	Rear Left Door Proector Chrome		DL	\$ 180.00	✓
8	Rear Left Door Hingh	11 2	\$ 160.00	\$ 320.00	X
9	Rear Left Door Inner Trim Board		11	\$ 520.00	X
10	Rear Left Door Power Window Motor Assy		gentle	\$ 500.00	✓ 295.00
11	Rear Left Door Inner Rubber		11	\$ 160.00	X
12	Rear Left Fender		R	\$ 1,600.00	X
13	Rear Left Rocket panel Garnish		cut	\$ 280.00	✓
14	Rear Left Cabin Fender		body	\$ 950.00	✓
15	Rear Left Rim Nut Cover		C16	\$ 150.00 SN	25 S.W
16	Company & Body Sticker		nu	\$ 400.00 SN	280 S.W
				107	
	not Authorized				
	date				1-5635
	30/9/20				107
	take photo after repair				9-5071.50
					5.11 325.00
					1-1680.00
					7280.50
					5800

date rec'd

Labour					
1	Transfer Front Door			\$ 150.00	50
2	Transfer Rear Door			\$ 150.00	50
3	Check Wiring			\$ 80.00	max
4	Anti Rust Proof			\$ 100.00	80
5	Panel Beating			\$1,200.00	900
6	Paint Work			\$1,200.00	800

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #01-03 01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: