

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010450/ATF3E2

Date: 23/03/2021

REFERENCE

Insured/Claimant:	JIANG MINGXIA	Policy No:	2070117315		
Date of Loss:	25/09/2020	Nature of Claim:	OD	Claim No:	8443247015SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU4060K		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD896309
Reg. Date:	12/08/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF37L1109540
Colour:	White	Odometer:	715 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$142,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,422.00	6,384.24	25,037.76	79.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,887.00	6,002.00	14,885.00	71.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,309.00	12,386.24	39,922.76	76.32
- Excess (S\$)	3,600.00	3,600.00	0.00	0.00
(S\$)	48,709.00	8,786.24	39,922.76	81.96
+ GST 7.00/7.00% (S\$)	3,409.63	615.04	2,794.59	81.96
Nett Amount (S\$)	52,118.63	9,401.28	42,717.35	81.96

INSPECTION

Date of Assignment:	30/09/2020		
Date Inspected:	29/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,045.00 FS	*1,634.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	58.00 FS	*- FS
3	1		*FRONT SPOILER	Cut	379.00 FS	*303.20 FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	151.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - RH	Not Necessary	109.00 FS	*- FS
6	2		*FRONT WHEEL COVER - LH / RH	N/S Necessary / O/S Cut	530.00 FS	*424.00 FS
7	1		*FRONT BUMPER GUIDE SECTON - RH	Cracked	38.00 FS	*30.16 FS
8	1		*FRONT FENDER - RH	Dented	1,271.00 FS	*1,016.80 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
10	1		*FRONT FENDER BRACE - RH	Bent	87.00 FS	*68.96 FS
11	1		*FRONT FENDER BRACKET - RH	Bent	31.00 FS	*24.56 FS
12	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	237.00 FS	*- FS
13	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	100.00 FS	*- FS
14	1		*HEADLIGHT MOUNTING - RH	Cracked	117.00 FS	*93.60 FS
15	1		*LED HEADLIGHT - RH	Not Necessary	5,526.00 FS	*- FS
16	1		*LIFT CYLINDER - RH	Not Necessary	208.00 FS	*- FS
17	1		*FRONT DOOR - RH	Repair	2,542.00 FS	*- FS
18	1		*FRONT DOOR OUTER SEAL	Not Necessary	164.00 FS	*- FS
19	1		*FRONT DOOR CATCH	Not Necessary	119.00 FS	*- FS
20	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS
21	1		*FRONT DOOR COVER - RH	Not Necessary	265.00 FS	*- FS
22	1		*EXTERIOR MIRROR MOUNTING - RH	Cut	2,041.00 FS	*1,632.80 FS
23	1		*MIRROR CAP - RH	Cut	167.00 FS	*133.20 FS
24	1		*MIRROR GLASS - RH	Not Necessary	977.00 FS	*- FS
25	1		*EXTERIOR DOOR HANDLE - RH	Repair	701.00 FS	*- FS
26	1		*DOOR HANDLE CAP	Not Necessary	27.00 FS	*- FS
27	1		*REAR DOOR - RH	Repair	2,639.00 FS	*- FS
28	1		*REAR DOOR OUTER SEAL	Not Necessary	134.00 FS	*- FS
29	1		*REAR DOOR CATCH	Not Necessary	119.00 FS	*- FS
30	1		*SILL PANEL SEAL - RH	Not Necessary	134.00 FS	*- FS
31	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	307.00 FS	*- FS
32	1		*REAR DOOR COVER - RH	Cut	254.00 FS	*202.80 FS
33	1		*REAR FENDER - RH	Repair	3,204.00 FS	*- FS
34	1		*SIDE WINDOW - RH	Not Necessary	607.00 FS	*- FS
35	1		*REAR BUMPER	Not Necessary	1,465.00 FS	*- FS
36	1		*REAR BUMPER SPOILER	Not Necessary	454.00 FS	*- FS
37	1		*REAR BUMPER FIXING PARTS	Not Necessary	209.00 FS	*- FS
38	1		*REAR CROSS REINFORCEMENT - CENTRE	Not Necessary	96.00 FS	*- FS
39	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	63.00 FS	*- FS
40	1		*REAR CROSS PANEL	Not Necessary	308.00 FS	*- FS
41	1		*REAR WHEEL COVER - LH / RH	O/S Cut	530.00 FS	*212.00 FS
42	1		*ALUMINIUM RIM - RH FRONT / REAR	Front Cut	1,512.00 FS	*604.80 FS
43	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
44	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
45	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
46	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
47	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
48	1		*SUNDRIES	Necessary	400.00 FS	*2.56 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 31,422.00 6,384.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS AND REINSTALL ALL PARTS REMOVED	New	3,000.00	1,500.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, RHS WING MIRROR COVER AND DOOR HANDLE	New	3,000.00	2,450.00
6	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
7	TO RENEW RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	0.00
8	TO INSTALL SOLAR FILM FOR RHS REAR 1/4 GLASS	New	400.00	0.00
9	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS	New	200.00	0.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
11	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
12	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD RHS REAR FENDER AND REAR OUTER END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,500.00	500.00
13	TO RESPRAY REAR BUMPER, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	3,575.00	550.00
14	TO RENEW RHS FRONT RIM AND RHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT	New	320.00	280.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			20,887.00	6,002.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >