

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20010451/AQF3E2

**Date:** 21/01/2021

### REFERENCE

Insured/Claimant:	JIN LI	Policy No:	2070125093		
Date of Loss:	24/09/2020	Nature of Claim:	OD	Claim No:	5801143327SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8396R		
Make & Model:	AUDI A6, 2.0 TFSI (A)	Engine No:	DKY005146
Reg. Date:	26/08/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF28LN030104
Colour:	Black	Odometer:	2107 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$165,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,247.00	2,010.48	16,236.52	88.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,772.00	1,522.00	1,250.00	45.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,019.00</b>	<b>3,532.48</b>	<b>17,486.52</b>	<b>83.19</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	20,219.00	2,732.48	17,486.52	86.49
<b>+ GST 7.00/7.00% (S\$)</b>	1,415.33	191.27	1,224.06	86.49
<b>Nett Amount (S\$)</b>	<b>21,634.33</b>	<b>2,923.75</b>	<b>18,710.58</b>	<b>86.49</b>

### INSPECTION

Date of Assignment:	30/09/2020		
Date Inspected:	29/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,763.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	643.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTRE	Not Necessary	220.00 FS	*- FS
4	1		*FRONT BUMPER ADAPTER - LH	Cracked	39.00 FS	*30.88 FS
5	1		*FRONT BUMPER REINFORCEMENT BRACKET - LH	Not Necessary	110.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	151.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Cracked	208.00 FS	*166.00 FS
8	1		*FRONT BUMPER SPOILER	Not Necessary	249.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	429.00 FS	*- FS
10	1		*FRONT BUMPER SIDE AIR GUIDE - LH LOWER	Not Necessary	28.00 FS	*- FS
11	1		*FRONT BUMPER SIDE AIR GUIDE - LH UPPER	Not Necessary	21.00 FS	*- FS
12	1		*RADIATOR GRILLE	Cut	2,192.00 FS	*1,753.60 FS
13	1		*RADIATOR GRILLE COVER	Not Necessary	54.00 FS	*- FS
14	1		*RADIATOR GRILLE COVER CAP	Not Necessary	88.00 FS	*- FS
15	1		*RADIATOR GRILLE BRACKET	Not Necessary	92.00 FS	*- FS
16	1		*FRONT BUMPER CARRIER	Not Necessary	960.00 FS	*- FS
17	2		*FRONT BUMPER SUPPORT	Not Necessary	59.00 FS	*- FS
18	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	44.00 FS	*- FS
19	1		*FRONT BUMPER BRACKET - LH	Not Necessary	54.00 FS	*- FS
20	1		*FRONT BUMPER COVER	Not Necessary	124.00 FS	*- FS
21	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	223.00 FS	*- FS
22	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
23	1		*HORN - LH LOW TONE	Not Necessary	214.00 FS	*- FS
24	1		*SPRING SHACKLE - LH	Not Necessary	47.00 FS	*- FS
25	2		*FRONT PARKING AID SENSOR	Not Necessary	-	-
26	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
27	1		*WHEEL SPOILER - LH	Not Necessary	164.00 FS	*- FS
28	1		*HEADLIGHT MOUNTING - LH	Not Necessary	117.00 FS	*- FS
29	1		*LED HEADLIGHT - LH	Not Necessary	8,432.00 FS	*- FS
30	1		*LIFT CYLINDER - LH	Not Necessary	196.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE - LH	Not Necessary	38.00 FS	*- FS
32	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
33	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 18,247.00 2,010.48**

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	New	400.00	-
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	800.00	500.00
4	TO RESPRAY FRONT BUMPER.	New	1,100.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,772.00</b>	<b>1,522.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >