

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20010472/T1QF3Q2

Date: 20/11/2020

REFERENCE

Insured/Claimant: MEI PEI PEI Policy No: DMPCSNW00048072001

Date of Loss: 29/09/2020 Nature of Claim: OD Claim No: SNM20D203587C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8846H		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030983615
Reg. Date:	22/05/2017 (Man. Year: 2017)	Chassis No:	WDD2050402R286715
Colour:	White	Odometer:	43893 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/70 R16	Rear Tyre Size:	205/70 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,675.99	11,393.60	6,282.39	35.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,140.00	1,630.00	2,510.00	60.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,815.99	13,023.60	8,792.39	40.30
Approved Total (Overridden) (S\$)		10,400.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
Nett Amount (S\$)	21,315.99	9,900.00	11,415.99	53.56

INSPECTION

Date of Assignment: 30/09/2020

Date Inspected: 30/09/2020 Inspected At:

BLK 1 KAKI BUKIT AVE 6 #02-57
Repairer: Yi Heng Motor Workshop
(HQ)

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2020)
Parts: 143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8846H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Repair	1,322.50 F	*- F
2	2		*BONNET LOCK (WCP)	Not Necessary	92.00 F	*- F
3	2		*BONNET SPRING (WCP)	Not Necessary	43.70 F	*- F
4	2		*BONNET STRIKER (WCP)	Not Necessary	48.30 F	*- F
5	1		*BONNET CATCH HOOK (WCP)	Not Necessary	48.30 F	*- F
6	1		*BONNET CATCH STRIKER (WCP)	Not Necessary	55.20 F	*- F
7	1		*BONNET HEAT LINING (WCP)	Not Necessary	161.00 F	*- F
8	8		*BONNET HEAT LINING CLIPS (WCP)	Not Necessary	65.00 F	*- F
9	2		*HEADLAMP (WCP)	Cracked	3,910.00 F	*3,910.00 F
10	2		*HRADLAMP BRACKET (WCP)	Cracked	287.50 F	*287.50 F
11	1		*FRONT GRILLE (WCP)	Cracked	145.00 F	*145.00 F
12	2		*FRONT GRILLE CLIPS (WCP)	Necessary	10.00 F	*10.00 F
13	1		*FRONT GRILLE NET (WCP)	Deformed	145.00 F	*145.00 F
14	1		*FRONT GRILLE LOGO (WCP)	Missing	201.25 F	*201.25 F
15	1		*FRONT GRILLE LOGO GARNISH (WCP)	Cracked	85.00 F	*85.00 F
16	1		*FRONT GRILLE CHROME (TOP) (WCP)	O/S Cut / N/S Not Necessary	108.10 F	*54.05 F
17	1		*FRONT GRILLE CHROME (BOTTOM) (WCP)	O/S Cut / N/S Not Necessary	112.00 F	*56.00 F
18	1		*FRONT LICENCE PLATE BASE GARNISH (WCP)	Missing	212.00 F	*212.00 F
19	1		*FRONT BUMPER (WCP)	Deformed	977.50 F	*977.50 F
20	10		*FRONT BUMPER CLIPS (WCP)	Necessary	50.00 F	*50.00 F
21	1		*FRONT BUMPER TOW COVER (WCP)	Missing	58.00 F	*58.00 F
22	1		*FRONT BUMPER SENSOR (CENTRE RIGHT) (WCP)	Distorted	149.50 F	*149.50 F
23	1		*FRONT BUMPER SPONGE (WCP)	Cracked	109.25 F	*109.25 F
24	1		*FRONT BUMPER GRILLE BEAM (WCP)	Cracked	280.00 F	*280.00 F
25	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	281.75 F	*281.75 F
26	2		*FRONT BUMPER REINFORCEMENT BRACKET (WCP)	Not Necessary	276.00 F	*- F
27	1		*FRONT BUMPER LOWER GRILLE (WCP)	Deformed	86.25 F	*86.25 F
28	1		*FRONT BUMPER LOWER TRAY (WCP)	Cracked	145.00 F	*145.00 F
29	1		*FRONT BUMPER LOWER DEFUSER (WCP)	Deformed	185.00 F	*185.00 F
30	1		*FRONT BUMPER LOWER DEFUSER CHROME (WCP)	Cracked	158.30 F	*158.30 F
31	2		*FRONT BUMPER SIDE ATTACHMENT (WCP)	Not Necessary	110.50 F	*- F
32	1		*FRONT BUMPER SIDE GARNISH (WCP)	O/S Deformed /N/SNot Necessary	92.00 F	*46.00 F
33	2		*PRE COLLISION SENSOR (WCP)	Not Working	240.00 F	*240.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*FRONT SUPPORT PANEL (WCP)	Repair	580.10 F	*- F
35	1		*FRONT SUPPORT TOP GARNISH (WCP)	Not Necessary	45.10 F	*- F
36	6		*FRONT SUPPORT TOP GARNISH CLIPS (WCP)	Not Necessary	30.00 F	*- F
37	1		*AIR-CON CONDENSOR (WCP)	Dented	920.00 F	*920.00 F
38	1		*RADIATOR ASSY (WCP)	Not Necessary	563.50 F	*- F
39	1		*WATER COOLER (WCP)	Not Necessary	630.00 F	*- F
40	2		*FRONT FENDER (WCP)	Not Necessary	1,127.00 F	*- F
41	20		*FRONT FENDER INNER COWLING CLIPS (WCP)	Not Necessary	100.00 F	*- F
42	1		*FRONT LICENCE PLATE (EMBOSS)	Bent	55.00 FS	*45.00 FS
43	1		*FRONT GRILE AIR GUIDE (WCP)	Deformed	138.00 F	*138.00 F
44	1		*FRONT BUMPER BEAM TOP GARNISH (WCP)	Deformed	110.00 F	*110.00 F
45	1		*FRONT BUMPER RADAR SENSOR CONTROL UNIT (WCP)	Cut	828.00 F	*828.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	15,377.60	9,913.35
+ Margin on L,N Items 15.00/15.00% (S\$)	2,298.39	1,480.25
Total Parts (S\$)	17,675.99	11,393.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	80.00	30.00
2	TO APPLY UNDERSEALING ON AFFECTED AREAS	New	220.00	0.00
3	TO REMOVE/REFIX AIR-CONDENSOR ,PIPNG SYSTEM AND TOP UP GAS	New	280.00	100.00
4	TO REMOVE/REFIX RADIATOR ASSY & CONDUCT PRESSURE TEST	New	250.00	0.00
5	TO REMOVE/REFIX HEADLAMP CONTROL UNIT AND REALIGNMENT LIGHTING SYSTEM	New	280.00	0.00
6	TO REPROGRAMME HEADLAMP ASSY	New	450.00	100.00
7	TO REPROGRAMME RE-COLLISION SENSOR AND RESET	New	380.00	200.00
8	TO REPLACE NEW PARTS ,CUT ,WELD ,KNOCK ETC	New	1,100.00	600.00
9	TO RESPRAY ON AFFECTED AREA	New	1,100.00	600.00
Gross Labour Cost (S\$)			4,140.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >