



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5535D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LIGHT, REVERSE: LED, FOR VOLVO B9TL BUS (DISC 10%)	CRUMPLED	647.08	582.37
1	LIGHT, TAIL: STOP, LED, FOR VOLVO B9TL BUS (DISC 10%)	CRUMPLED	519.83	467.85
1	LAMP, REFLECTOR: RED, FOR VOLVO B9TL BUS (DISC 10%)	CRUMPLED	9.95	8.96
1	EXT REAR O/S CORNER (DISC 10%) (ADDITIONAL)	CRUMPLED	1,556.60	1,400.94
1	LIGHT, INDICATOR: LED , FOR VOLVO B9TL BUS (DISC 10%) (ADDITIONAL)	CRUMPLED	519.83	467.85
1	SMRT STICKER (SN)	NECESSARY	75.00	75.00
1	O/S LOWER ENGINE ACC	SERVICEABLE	3,443.25	-
1	SEALED LEVER LATCH	TO REPAIR SEE LABOUR	143.00	-
			6,914.54	3,002.97
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF SEALED LEVER LATCH.		1,060.00	1,060.00
	TO PUTTY & RESPRAY.		772.00	602.00
			1,832.00	1,662.00
	GRAND TOTAL		8,746.54	4,664.97
	RECOMMENDED COST OF REPAIRS			4,664.97

Report Ref No. CS/UOI20010474/Qsd3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.