

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010482/ASD3E2

Date: 12/04/2021

REFERENCE

Insured/Claimant:	CHONG GUAN KEAT	Policy No:	1900084874-01	
Date of Loss:	29/09/2020	Nature of Claim:	OD	Claim No: 4168473829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL3323E		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK076864
Reg. Date:	09/04/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF59KA029348
Colour:	Black	Odometer:	27539 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$156,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,530.00	16,210.08	10,319.92	38.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,122.00	12,672.00	8,450.00	40.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	47,652.00	28,882.08	18,769.92	39.39
+ GST 7.00/7.00% (S\$)	3,335.64	2,021.75	1,313.89	39.39
Nett Amount (S\$)	50,987.64	30,903.83	20,083.81	39.39

INSPECTION

Date of Assignment:	30/09/2020		
Date Inspected:	30/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	17.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,504.00 FS	*2,003.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	163.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	220.00 FS	*176.00 FS
4	1		*REAR BUMPER CHROME TRIM	Cracked	1,005.00 FS	*804.00 FS
5	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	82.00 FS	*- FS
6	2		*LED TAILLIGHT-LH/RH OUTER	Cut	2,258.00 FS	*1,806.40 FS
7	2		*TAIL LIGHT TRIM-LH/RH OUTER	Deformed	60.00 FS	*46.72 FS
8	2		*LED TAIL LIGHT-LH/RH INNER	Cracked	2,016.00 FS	*1,612.80 FS
9	2		*TAIL LIGHT TRIM-LH/RH INNER	Cut	60.00 FS	*46.72 FS
10	2		*LED LICENSE PLATE LIGHT	Cracked	100.00 FS	*79.52 FS
11	1		*ADDITIONAL BRAKE LIGHT	Damaged	570.00 FS	*455.60 FS
12	2		*REAR PARKING AID SENSOR-INNER/OUTER (NPA)	Not Necessary	0.00 FS	*- FS
13	1		*REAR BUMPER CARRIER	Not Necessary	886.00 FS	*- FS
14	2		*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*- FS
15	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	44.00 FS	*- FS
16	1		*REAR LID	Dented	3,080.00 FS	*2,464.00 FS
17	2		*REAR LID HINGE-LH/RH	Not Necessary	452.00 FS	*- FS
18	1		*REAR LID ATTACHMENT PARTS	Not Necessary	152.00 FS	*- FS
19	1		*REAR LID LOCK	Jammed	241.00 FS	*192.80 FS
20	1		*BONNET LOCK COVER	Cut	12.00 FS	*9.60 FS
21	1		*REAR LID FLAP GASKET	Necessary	234.00 FS	*186.80 FS
22	1		*LID LOCK PUSH BUTTON	Cracked	1,330.00 FS	*1,064.00 FS
23	1		*REAR LID STRIKER PLATE	Not Necessary	63.00 FS	*- FS
24	1		*REAR LID SERVOMOTOR	Not Necessary	291.00 FS	*- FS
25	2		*REAR LID DRIVE UNIT	Not Necessary	3,584.00 FS	*- FS
26	1		*REAR LID BOWDEN CABLE	Not Necessary	57.00 FS	*- FS
27	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.40 FS
28	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.40 FS
29	1		*REAR WINDSCREEN	Necessary	1,155.00 FS	*924.00 FS
30	1		*PRIMER	Necessary	19.00 FS	*14.96 FS
31	1		*REAR CROSS PANEL	Dented	356.00 FS	*284.40 FS
32	1		*CROSS PANEL REINFORCEMENT	Dented	625.00 FS	*500.00 FS
33	1		*REAR LID TRIM PANEL	Cracked	441.00 FS	*352.80 FS
34	1		*REAR CROSS PANEL TRIM	Cracked	356.00 FS	*284.80 FS
35	1		*BOOT LID CONTROL UNIT	Not Necessary	399.00 FS	*- FS
36	1		*REAR NO PLATE	Cut	80.00 FS	*80.00 FS
37	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
38	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
39	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
40	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
41	1		*SUNDRIES	Necessary	350.00 FS	*77.60 FS
42	1		*A5 INSCRIPTION	Necessary	95.00 FS	*75.36 FS
43	1		*REAR FENDER REINFORCEMENT FOR D-PILLAR RHS	Dented	271.00 FS	*216.40 FS
44	1		*REAR FENDER REINFORCEMENT FOR D-PILLAR LHS	Dented	271.00 FS	*216.40 FS
45	1		*REAR FENDER INNER SIDE PANEL RHS	Buckled	203.00 FS	*162.40 FS
46	1		*REAR FENDER INNER SIDE PANEL LHS	Buckled	203.00 FS	*162.40 FS
47	1		*TAILLIGHT PANEL RHS	Buckled	162.00 FS	*129.20 FS
48	1		*TAILLIGHT PANEL LHS	Buckled	162.00 FS	*129.20 FS
49	1		*LUGGAGE COMPARTMENT TRIM LHS	Crumpled	1,034.00 FS	*827.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **26,530.00** **16,210.08**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	New	280.00	280.00
2	TO RENEW REAR WINDSCREEN TO FACILITATE REAR LID RENEWAL.	New	480.00	480.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	New	400.00	400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	New	200.00	150.00
5	TO DISLODGE ROOF LINING TO FACILITATE RENEWAL OR REAR LID HINGES.	New	280.00	0.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.CUT OUT AND WELD REAR END PANELLING,REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	New	3,500.00	1,000.00
7	TO RESPRAY REAR BUMPER,REAR LID,HINGES AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	New	2,750.00	1,650.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
9	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENDOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.	New	480.00	0.00
11	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
12	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	800.00
13	TO PUT ON VEHICLE ON CAR-O-LINER TO FACILITATE THE REPARING OF THE REAR PORTION	New	1,800.00	1,800.00
14	TO CUT OUT AND WELD BOTH TAILLIGHT PANELS, BOTH REAR FENDER INNER SIDE PANEL AND BOTH REAR FENDER REINFORCEMENT	New	6,000.00	3,000.00
15	TO RESPRAY BOTH TAILLIGHT PANELS AND SPARE WHEEL HOUSING	New	2,000.00	1,100.00
16	TO INSTALL STICKER FOR REAR BUMPER CHROME TRIM	New	200.00	60.00
Gross Labour Cost (S\$)			21,122.00	12,672.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >