

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010490/AQF3Q2

Date: 27/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00004992001
Claimant Vehicle No :	PC4234K	Insured Vehicle No :	CB6543P
Date of Loss:	29/09/2020	Nature of Claim:	TP
		Claim No:	SNM20D203588C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC4234K	Engine No:	1KD2561809
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Chassis No:	KDH2230025856
Reg. Date:	11/12/2015 (Man. Year: 2015)	Odometer:	468179 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,443.98	7,780.23	11,663.75	59.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,530.00	2,050.00	4,480.00	68.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,973.98	9,830.23	16,143.75	62.15
Approved Total (Overridden) (S\$)		7,800.00		
(S\$)	25,973.98	7,800.00	18,173.98	69.97
+ GST 7.00/7.00% (S\$)	1,818.18	546.00	1,272.18	69.97
Nett Amount (S\$)	27,792.16	8,346.00	19,446.16	69.97

INSPECTION

Date of Assignment:	30/09/2020	
Date Inspected:	30/09/2020 Inspected At:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4., #08-09 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jan 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC4234K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	571.60 FL	*571.60 FL
2	1		*FRONT BUMPER FOG LAMP COVER RH	Cracked	48.70 FL	*48.70 FL
3	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	295.80 FL	*- FL
4	1		*FRONT BUMPER TOWING COVER RH	Not Necessary	25.10 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	226.40 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER	Necessary	148.70 FL	*148.70 FL
7	1		*HEADLAMP	O/s Cracked	6,066.40 FL	*2,546.00 FL
8	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	38.80 FL	*- FL
9	1		*CENTRE GRILLE BASE	Cracked	568.90 FL	*568.90 FL
10	1		*CENTRE GRILLE LOWER COVER GARNISH	Not Necessary	383.70 FL	*- FL
11	1		*CENTRE GRILLE UPPER COVER GARNISH	Not Necessary	221.80 FL	*- FL
12	1		*FRONT WIPER GARNISH	Cut	639.80 FL	*639.80 FL
13	1		*FRONT WIPER GARNISH SIDE JOINT RH	Cut	26.80 FL	*26.80 FL
14	1		*FRONT WINDSCREEN MOULDING	Not Necessary	81.80 FL	*- FL
15	1		*BONNET	Dented	1,020.30 FL	*1,020.30 FL
16	1		*BONNET LOGO	Necessary	75.30 FL	*75.30 FL
17	1		*BONNET CORNER GARNISH RH	Cut	28.70 FL	*28.70 FL
18	1		*BONNET HINGE	O/s Bent	119.60 FL	*59.80 FL
19	1		*BONNET LOCK	Not Necessary	93.90 FL	*- FL
20	1		*AIR CLEANER	Cracked	780.01 FL	*780.01 FL
21	1		*AIR DUCT	Not Necessary	115.80 FL	*- FL
22	1		*FRONT BRAKE MASTER PUMP C/W FLUID CONTAINER	Not Necessary	840.70 FL	*- FL
23	1		*FRONT CORNER PANEL RH	Dented	268.40 FL	*268.40 FL
24	1		*FRONT CORNER PANEL TOP RUBBER RH	Not Necessary	24.50 FL	*- FL
25	1		*FRONT STEP PANEL GARNISH RH	Not Necessary	204.90 FL	*- FL
26	1		*FRONT DOOR PILLAR RH (OUTER)	Repair	542.80 FL	*- FL
27	1		*FRONT DOOR PILLAR RH (INNER)	Repair	317.20 FL	*- FL
28	1		*FRONT DOOR SIDE MIRROR RH (COMPLETE SET)	Cracked	1,492.90 FL	*1,150.00 FL
29	1		*FRONT DOOR RH	Dented	1,887.10 FL	*1,611.00 FL
30	1		*FRONT DOOR GLASS RH	Cut	525.30 FL	*525.30 FL
31	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	258.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*FRONT DOOR OUTERSTRIP RH	Cut	125.80 FL	*125.80 FL
33	1		*FRONT DOOR INNER LOCK RH	Not Necessary	578.30 FL	*- FL
34	1		*FRONT DOOR HINGE RH	Upper Bent	170.40 FL	*85.20 FL
35	1		*FRONT DOOR CHECKER RH	Not Necessary	183.80 FL	*- FL
36	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	926.10 FL	*- FL
37	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	288.10 FL	*- FL
38	1		*FRONT DOOR WIRE HARNESS RH	Not Necessary	245.90 FL	*- FL
39	1		*FRONT DOOR INNER TRIM RH	Not Necessary	806.20 FL	*- FL
40	1		*FRONT DOOR WIRE HOLDER RH	Not Necessary	105.20 FL	*- FL
41	1		*FRONT SHOCK ABSORBER RH	Not Necessary	127.90 FL	*- FL
42	1		*FRONT KNUCKLE ARM RH	Not Necessary	499.80 FL	*- FL
43	1		*FRONT KNUCKLE ARM BEARING RH	Not Necessary	367.10 FL	*- FL
44	1		*FRONT UPPER ARM RH	Not Necessary	1,160.90 FL	*- FL
45	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
46	1		*SET CENTRE GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
47	1		*SET FRONT WIPER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
48	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
50	1		*BONNET SEALANT	Not Necessary	120.00 FS	*- FS
51	1		*SET FRONT STEP PANEL GARNISH RH CLIP	Not Necessary	50.00 FS	*- FS
52	1		*FRONT DOOR PILLAR RH (OUTER) SEALANT	Not Necessary	120.00 FS	*- FS
53	1		*FRONT DOOR SEALANT RH	Not Necessary	120.00 FS	*- FS
54	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
55	1		*FRONT DOOR GLASS SOLAR FILM RH	Not Necessary	350.00 FS	*- FS
56	1		*FRONT WHEEL TYRE RH	Not Necessary	380.00 FS	*- FS
57	1		*FRONT WHEEL RIM RH	Not Necessary	250.00 FS	*- FS
58	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	25,325.31	10,350.31
- List Item Discount on L Items 25.00/25.00% (S\$)	5,881.33	2,570.08
Total Parts (S\$)	19,443.98	7,780.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,800.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	80.00
6	REMOVE AND REFIX BRAKE MASTER PUMP	New	350.00	0.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	TRANSFER FRONT DOOR MECHANISM	New	80.00	80.00
10	REMOVE AND REFIX DASHBOARD	New	850.00	0.00
11	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	0.00
12	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
13	REMOVE AND REFIX FRONT WHEEL BEARING	New	60.00	0.00
14	FOUR WHEEL ALIGNMENT	New	120.00	0.00
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			6,530.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >