



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007508
INV Date 10/11/2020
Reference CC4/FCI20010491/T1da3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. YQ 1638T
Insured Veh. SH 9667A
Claim No. D20003881MFSH
Policy No. D-20094922MFSH
Accident Date 18/09/2020
Inspection Date 26/10/2020

Description	Total
Survey Inspection	213.00
Digital Photographs	
Transportation	
Subtotal	213.00
GST (7%)	14.91
Grand Total	227.91

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20010491/T1da3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 10-11-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9667A	Veh. Inspected	YQ 1638T
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003881MFSH	Excess (\$)	0.00
Assign From	CHRIS LIM	Assign Date	30/09/2020

2. Vehicle Particulars & Condition

Make & Model	HINO	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHHUCV3H50K032144	Colour	WHITE
Odometer	20429	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	7.00 R16	BRIDGESTONE	6 mm
L/H Front Tyre	7.00 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	7.00 R16 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	7.00 R16 (D)	BRIDGESTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/09/2020	Inspection Date	26/10/2020
Survey held at	CENTRAL AUTOMOTIVE PTE LTD 1 SUNVIEW ROAD, #08-44, ECO-TECH@SUNVIEW, SINGAPORE 627615		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 1638T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	720.00	720.00
1	FRONT HEAD LAMP ASSY (RH)	CRACKED	580.00	580.00
1	FRONT SIDE PANEL (RH)	CUT	320.00	320.00
	LESS 10% DISCOUNT		-	-162.00
			1,620.00	1,458.00
	<u>LABOUR</u>			
	LUMP SUM LABOUR TO REMOVE AND INSTALL ALL ABOVE ITEMS INCLUDING TOOL AND MATERIAL.		600.00	400.00
	DRIVER RIGHT DOOR & REALIGNMENT (DOOR ARM SPRING REPAIR, REMOVE GLASS PANEL, SWITCH, ARMS, INSIDE PANEL, PANEL BEATING AND REFIX).		680.00	200.00
	RESPRAY DOOR AND TRUCK CABIN.		1,200.00	600.00
	ARTWORK FOR TRUCK CABIN.		280.00	180.00
			2,760.00	1,380.00
	GRAND TOTAL		4,380.00	2,838.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00

Report Ref No. CC4/FCI20010491/T1da3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YQ 1638T

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



