

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647.Singapore 542224

Email: [Winsongkk@hotmail.com](mailto:Winsongkk@hotmail.com) Contact: 9747 0063

Company Register No. 53326249J

---

Our Ref: WG/TP/2021-167  
Invoice No: TP/CTA/2021-167  
Vehicle No: YQ1638T  
Attn: GAN TECK KAR INVESTMENTS PTE LTD  
Company: CENTRAL AUTOMOTIVE PTE LTD  
Address: 1 Sunview Rd #07-20 Ecotech@Sunview . ( Jurong Pionner Rd ) Singapore 627615

Date 30 September 2021

## Invoice

Surveyor Fee: S\$360  
Re-inspection Fee: S\$80  
Transport: S\$60  
Photographs: S\$37/- (@ \$1 per photo, total 37 photos)  
Total: S\$537

Surveyor: Winson Sph  
Signature:   
Date: 30 September 2021



# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224  
Email: winsongkk@hotmail.com Contact: 9747 0063  
Company Register No. 53326249J

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : GAN TECK KAR INVESTMENTS PTE LTD  
C/O CENTRAL AUTOMOTIVE PTE LTD  
1 Sunview Rd #07-20 Ecotech@Sunview  
( Jurong Pioneer Rd ) Singapore 627615

Date : 30 September 2021  
Our Ref : WG/TP/2021-167

### REFERENCE PARTICULARS

Date of Accident : 18 September 2020  
Date of Inspection : 10 September 2021

Type of Inspection : Third Party Claim  
Date of Re-Inspn : Na

### VEHICLE PARTICULARS

Registration No : YQ1638T  
Make : HINO  
Model : XZU710R 14FT WIDE CAB 5T  
Year : 2019

Engine No : N04CVV10866  
Chassis No : JHHUCV3H50K032144  
Odometer : 42881km  
Colour : White

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size	Thread Balance
Front Near side	: Bridgestone	215/85R16	5 mm
Front Off Side	: Bridgestone	215/85R16	5 mm
Rear Near Side	: Bridgestone	215/85R16	5 mm
Rear off Side	: Bridgestone	215/85R16	5 mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front and front right portions..  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$6,300.00** nett at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five ( 05 ) working days.

Enclosed Thirty -seven ( 37 ) photographs depicting damage to the vehicle.

Inspection conducted at : CENTRAL AUTOMOTIVE PTE LTD  
1 Sunview Rd #07-20 Ecotech@Sunview . ( Jurong Pioneer Rd ) Singapore 627615

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : YQ1638T  
 MODEL : XZU710R 14FT WIDE CAB 5T

Our Ref : WG/TP/2021-167

**ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS**

**DESCRIPTION OF PARTS AND NATURE OF REPAIRS**

A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION		ORIGINAL QUOTATION	REVISED QUOTATION		
01	FRONT BUMPER	1	CRACKED	\$	1,427.00	\$	1,427.00 967.20	
02	FRONT BUMPERBRACKET LH	1	NECESSARY	\$	132.00	\$	- XNN	
03	FRONT BUMPER BRACKET RH	1	NECESSARY	\$	132.00	\$	132.00	
04	FRONT BUMPER INNER BRACKET	1	NOT NECESSARY	\$	211.00	\$	XNN -	
05	FRONT HEADLAMP RH	1	CRACKED	\$	1,451.00	\$	1,451.00 980	
06	FRONT CORNER PANEL RH	1	CRACKED	\$	581.00	\$	581.00 320	
07	FRONT FOG LAMP RH	1	NOT NECESSARY	\$	382.00	\$	-	
08	FRONT DOOR PANEL RH	1	DENTED	\$	2,563.00	\$	2,563.00 2200	
09	FRONT STEP GANRISH RH	1	GRAZED	\$	264.00	\$	264.00 XNN	
				\$	7,143.00	\$	6,418.00	
				Less 10%	\$	714.30	\$	641.80
				\$	6,428.70	\$	5,776.20	
							4599.20	
							4139.28	

**B) S/NETT ITEM**

10 FRONT BUMPER CLIP 1 SET NECESSARY

\$	30.00	\$	20.00
\$	30.00	\$	20.00

20

**Parts Total :**

\$	6,458.70	\$	5,796.20
----	----------	----	----------

**C) LABOUR CHARGES & MISC**

11 CHECK FRONT WIRING AND LIGHTNING SYSTEM  
12 TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW  
13 PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS  
14 SPRAY PAINTING ON AFFECTED AREAS  
15 APPLY ANTI RUST ON AFFECTED AREAS  
16 REMOVE AND RENEW STICKERS ON AFFECTED AREAS

\$	90.00	\$	80.00	30
\$	250.00	\$	200.00	60
\$	600.00	\$	500.00	
\$	1,200.00	\$	1,000.00	600
\$	200.00	\$	30	180.00
\$	150.00	\$	130.00	

**Labour Total :**

\$	2,490.00	\$	2,090.00
----	----------	----	----------

1350

**Total Parts and Laboure :**

\$	8,948.70	\$	7,886.20
----	----------	----	----------

**FINAL LUMP SUM ADJUSTMENT**

\$	6,300.00
----	----------

5509.28

L/\$4400

4 DAYS

**POINT OF IMPACT**

The impact was confined to the front right portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

**ADJUSTMENT/RECOMMENDATIONS**

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

**CONCLUSION**

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$6,300.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
WG APPRAISAL SERVICES



Winson Goh  
Automotive Appraiser



















