

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010492/ATF3E2

Date: 04/03/2021

REFERENCE

Insured/Claimant:	NEVAJ KOCHHAR	Policy No:	1900080709		
Date of Loss:	26/09/2020	Nature of Claim:	OD	Claim No:	8921547036SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK2170S		
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Engine No:	CHZC27230
Reg. Date:	29/03/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8VXK1022681
Colour:	Black	Odometer:	9721 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,907.00	6,756.80	5,150.20	43.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,637.00	11,007.00	2,630.00	19.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,544.00	17,763.80	7,780.20	30.46
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	24,944.00	17,163.80	7,780.20	31.19
+ GST 7.00/7.00% (S\$)	1,746.08	1,201.47	544.61	31.19
Nett Amount (S\$)	26,690.08	18,365.27	8,324.81	31.19

INSPECTION

Date of Assignment:	30/09/2020		
Date Inspected:	30/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	13.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,944.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Not Necessary	234.00 FS	*- FS
4	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	16.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR - RH	Not Necessary	41.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	66.00 FS	*- FS
7	1		*REAR FENDER - RH	Dented	2,305.00 FS	*1,844.00 FS
8	1		*REAR WINDSCREEN	Necessary	805.00 FS	*643.60 FS
9	1		*SIDE WINDOW - RH	Necessary	563.00 FS	*450.40 FS
10	1		*PRIMER	Necessary	19.00 FS	*14.96 FS
11	1		*WHEEL HOUSING LINER - RH	Not Necessary	237.00 FS	*- FS
12	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
13	1		*REAR DOOR - RH	Distorted	2,494.00 FS	*1,995.20 FS
14	1		*REAR DOOR OUTER SEAL	Necessary	159.00 FS	*126.80 FS
15	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
16	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
17	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	127.00 FS	*- FS
18	1		*REAR DOOR CATCH	Not Necessary	93.00 FS	*- FS
19	1		*REAR DOOR INNER SEAL	Not Necessary	189.00 FS	*- FS
20	1		*REAR ALUMINIUM RIM - RH	Cut	699.00 FS	*558.80 FS
21	1		*REAR WHEEL SPOILER - RH	Necessary	35.00 FS	*27.36 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
23	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
24	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
25	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
26	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
27	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
28	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
29	1		*SUNDRIES	Necessary	350.00 FS	*15.68 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,907.00 6,756.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	0.00
3	TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS REAR 1/4 GLASS	New	400.00	400.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
6	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
8	TO REMOVE AND REINSTALLLL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
9	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	3,000.00
10	TO RESPRAY REAR BUMPER, RHS REAR DOOR, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENTS AND JOINT SEALER WORKS	New	4,125.00	3,025.00
11	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL	New	280.00	280.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			13,637.00	11,007.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >