

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20010501/UGS3Q2

**Date:** 13/01/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SGZ5454X	<b>Insured Vehicle No :</b>	SHA7924M
Date of Loss: 29/09/2020	Nature of Claim: TP	Claim No: MCT20090478

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ5454X		
Make & Model:	HONDA JAZZ, 1.3 CVT (A)	Engine No:	L13B15000399
Reg. Date:	15/01/2020 (Man. Year: 2019)	Chassis No:	JHMGK3850LS216814
Colour:	Red	Odometer:	12938 km
Engine Capacity:	1318 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,805.40	2,283.96	4,521.44	66.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,500.00	1,570.00	51.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>9,875.40</b>	<b>3,783.96</b>	<b>6,091.44</b>	<b>61.68</b>
<b>Approved Total (Overridden) (\$)</b>		<b>3,000.00</b>		
<b>(S\$)</b>	9,875.40	3,000.00	6,875.40	69.62
<b>+ GST 7.00/7.00% (S\$)</b>	691.28	210.00	481.28	69.62
<b>Nett Amount (S\$)</b>	<b>10,566.68</b>	<b>3,210.00</b>	<b>7,356.68</b>	<b>69.62</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,417.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,400.00</b>		

### INSPECTION

Date of Assignment:	30/09/2020	
Date Inspected:	01/10/2020 Inspected At:	Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2020)
<b>Parts:</b>	144	HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGZ5454X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	683.60 FL	*549.20 FL
2	2		*FRONT BUMPER SIDE RETAINER -L/R	Not Necessary	91.00 FL	*- FL
3	1		*REAR DOOR -LH	Bent / Warped	861.90 FL	*745.30 FL
4	1		*REAR DOOR OUTER HANDLE	Not Necessary	182.30 FL	*- FL
5	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	131.60 FL	*- FL
6	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	154.80 FL	*- FL
7	1		*REAR DOOR GLASS REGULATOR	Not Necessary	481.60 FL	*- FL
8	1		*REAR DOOR MOTOR	Not Necessary	130.20 FL	*- FL
9	1		*REAR DOOR INNER LOCK	Not Necessary	361.90 FL	*- FL
10	1		*REAR DOOR W/STRIP	Not Necessary	141.20 FL	*- FL
11	1		*REAR FENDER -LH	Badly Dented / Buckled	891.70 FL	*891.70 FL
12	1		*REAR FENDER INNER SHIELD	Not Necessary	146.20 FL	*- FL
13	1		*REAR FENDER GLASS MOULDING	No such part	89.60 FL	*- FL
14	1		*REAR SHOCK ABSORBER -LH	Not Necessary	341.60 FL	*- FL
15	1		*REAR WHEEL HUB BEARING	Not Necessary	561.90 FL	*- FL
16	1		*REAR AXLE BEAM	Not Necessary	1,586.90 FL	*- FL
17	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
18	1		*SET REAR FENDER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
19	1		*SET REAR DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS
20	1		*REAR SPORT WHEEL -LH	Cut	800.00 FS	*400.00 FS
21	1		*REAR TYRE -LH	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,173.00</b>	<b>2,721.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,367.60	437.24
<b>Total Parts (\$\$)</b>	<b>6,805.40</b>	<b>2,283.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE ,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	80.00
3	TO REMOVE ,REFIX REAR UNDERCARRIAGE	New	350.00	0.00
4	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
5	TO RESPRAY UNDERCOATING	New	120.00	60.00
6	TO RESPRAY PAINTING AND ETC	New	1,080.00	600.00
7	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	680.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,070.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >