

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC4/11/200/2501/4953

ASSIGNMENT

From:

Date:

Estimated Cost:

OD *DP* / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGZ5454X

at Workshop m/s

AIM

of

Insured:

SHA7924M

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

66k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4
20

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

32H

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

*LTA 35136**7/10/20 Confirmed 2/5 & 3000w to kelvin*

Veh No:

SGZ5454X

Yr Regn:

1/20

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A /

Make:

Honda Jazz

C.C

1318

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

12938

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHM6K3850LS 216814

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Border~~ / Jammed / Leaked / Burnt orBrake: ~~Border~~ / Jammed / Leaked / Burnt orModi: ~~NI~~ / S/Rim / STD A/Rim or

Tyre Size:

F:

175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOKO

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/9/20

D.O.I.

1/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS SI☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

aka Cecilia

ESTIMATE

Our Ref: AC20056/TP/SGZ5454X-29.09.2020

Vehicle number: SGZ5454X

Vehicle Make & Model: HONDA JAZZ

not Authorized
claim
1/5 & 3000/
Hdags.
The following

Items	Qty	List Items	Amount \$
1	1	Rear bumper	683.60 ✓
2	2	Front bumper side retainers - L/R @ 45.50	91.00 X
3	1	Rear door - LH	861.90 ✓
4	1	Rear door outer handle	182.30 X
5	1	Rear door glass outer moulding	131.60 X
6	1	Rear door glass run channel	154.80 X
7	1	Rear door glass regulator	481.60 X
8	1	Rear door motor	130.20 X
9	1	Rear door inner lock	361.90 X
10	1	Rear door w/strip	141.20 X
11	1	Rear fender - LH	891.70 ✓
12	1	Rear fender inner shield	146.20 X
13	1	Rear fender glass moulding	89.60 X
14	1	Rear shock absorber - LH	341.60 X
15	1	Rear wheel hub bearing	561.90 X
16	1	Rear axle beam	1,586.90 X
Sub-total			6,838.00
Less 20%			1,367.60
Total List			5,470.40

Special Nett Items			
17	1 set	Rear bumper clip	35.00 ✓
18	1 set	Rear fender glass sealant	80.00 40
19	1 set	Rear door black tape	120.00 60
20	1	Rear sport wheel - LH	800.00 400
21	1	Rear tyre - LH	300.00 X
Total Special Nett			1,335.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:
Page 1 of 2

P-2186.20
20%
P-1748.96
SW-535.00
L-1500.00
3783.96
23
3027

Vehicle number: SGZ5454X

Vehicle Made & Model: HONDA JAZZ

Labour charges

22	To check rear electrical wiring	50.00	20
23	To remove, refix rear interior trims to assist repair	150.00	80
24	To remove, refix rear undercarriage	350.00	X
25	To check wheel alignment	120.00	60
26	To respray undercoating	120.00	60
27	To respray painting and etc	1,080.00	600
28	Panel beating, cut, weld remove & replacing above parts	1,200.00	680
Total Labour		3,070.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

9,875.40