

(08/11/13) wef
ASS. REC. BY: *Marcus*

REF: *CC6/FC120010502/UKa3*

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SML 6925A*
at Workshop m/s *Yew Tee*
of _____
Insured: *SMC 71809*
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *80k.*
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *4* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

694C
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SML 6925A* Yr Regn: *30/5/19*
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
Make: *Honda Freed Hybrid* *1496*
Colour: *Silver* A/C: *Insured / Std / NI / NA*
Sp. Reading: *147142* T/Radio: *Insured / Std / NI / NA*
Eng/No: _____
C/No: *GB7 1080201*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: *In order* / Jammed / Leaked / Burnt or
Brake: *In order* / Jammed / Leaked / Burnt or
Modi: *AM* / S/Rim / STD A/Rim or
Tyre Size: F: *185/65 R15*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Tourador*
Front *6* mm Rear *6* mm
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. *27/9/20* D.O.I. *1/10/20*
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S H/L, N/S body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 56881

3/10/20 4/5 @ 3200 conf. and with May

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS, SI
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

TOTAL

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : FIRST CAPITAL INSURANCE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTKB/TP/2009/010
Policy No:	B29126381MCX	Date of Loss:	27/09/2020
Vehicle Reg. No.:	SML6925A	Driveable?	yes
Driver Age:	0000-00-00	Third Party Vehicle No.:	SHC7180G
Any Injuries?	no	Contact No:	
Insured/Claimant:	ADVANCE LIMO & RENTAL PTE LTD	Driver:	KOH WEE TECK
Make/Model:	Honda, Freed - GB31	Vehicle Reg. Date:	30 May 2019
Vehicle Colour:	Silver	Engine Number:	LEB5616503
Chassis No:	GB71080201	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	8

Description of Accident/loss REFER TO GIA REPORT

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS	Amount
Parts	6,464.96
Miscellaneous Items	1,800.40
Labour	1,330.00
Paintwork Labour	1,350.00
Towing	0.00
Gross Total(S\$):	10,945.36
GST 7.00%(S\$):	766.18
Nett Amount(S\$):	11,711.54

This claim is handled by: may chai

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Advised
LKK
2/5/2020
4 days.
The 2nd Advisor

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>R</i>	1,050.40	-20.00	840.32 <i>X</i>
2	1	FRONT FENDER LH <i>R</i>	440.20	-20.00	352.16 <i>X</i>
3	1	FRONT FENDER EMBLEM LH <i>del</i>	65.90	-20.00	52.72 <i>✓</i>
4	1	FRONT DOOR LH <i>Bent/warped</i>	950.40	-20.00	760.32 <i>✓</i>
5	1	FRONT DOOR INNER BOARD LH <i>11</i>	680.40	-20.00	544.32 <i>X</i>
6	1	FRONT DOOR LOCK LH <i>11</i>	262.40	-20.00	209.92 <i>X</i>
7	1	FRONT DOOR SIDE MIRROR LH <i>cne</i>	580.40	-20.00	464.32 <i>✓</i>
8	1	FRONT DOOR SIDE MIRROR COVER LH <i>cne</i>	98.20	-20.00	78.56 <i>✓</i>
9	1	FRONT DOOR SIDE MIRROR SIGNAL LAMP LH <i>cne</i>	330.50	-20.00	264.40 <i>✓</i>
10	1	FRONT DOOR HINGE TOP <i>11</i>	59.40	-20.00	47.52 <i>X</i>
11	1	FRONT DOOR HINGE BOTTOM <i>11</i>	59.40	-20.00	47.52 <i>X</i>
12	1	REAR DOOR LH <i>Bent/warped</i>	985.40	-20.00	788.32 <i>✓</i>
13	1	REAR DOOR INNER BOARD LH <i>11</i>	680.40	-20.00	544.32 <i>X</i>
14	1	REAR FENDER LH <i>R</i>	912.40	-20.00	729.92 <i>X</i>
15	1	REAR BUMPER <i>R</i>	925.40	-20.00	740.32 <i>X</i>

Total Parts (\$\$) 6,464.96

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT WHEEL RIM LH <i>11</i>	400.00	0.00	400.00 <i>X</i>
2	1	REAR WHEEL RIM LH <i>11</i>	400.00	0.00	400.00 <i>X</i>
3	1	FRONT TYRE LH <i>11</i>	300.00	0.00	300.00 <i>X</i>
4	1	REAR TYRE LH <i>11</i>	300.00	0.00	300.00 <i>X</i>
5	10	FRONT DOOR INNER BOARD CLIPS <i>11</i>	50.00	0.00	50.00 <i>X</i>
6	10	REAR DOOR INNER BOARD CLIPS <i>11</i>	50.00	0.00	50.00 <i>X</i>
7	1	FRONT LH WHEEL COVER <i>cut</i>	150.20	0.00	150.20 <i>60</i>
8	1	REAR LH WHEEL COVER <i>R</i>	150.20	0.00	150.20 <i>X</i>

Sub Total (\$\$) 1,800.40

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Dismantle and Refit Rear Fender Glass.	60.00	0.00 <i>11</i>	60.00 <i>X</i>
2	1	To Dismantle and Refit Sliding Door Glass.	100.00	0.00	100.00 <i>50</i>
3	1	To Transfer Sliding Door.	80.00	0.00	80.00 <i>50</i>
4	1	To Transfer Door.	80.00	0.00	80.00 <i>20</i>
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	100.00	0.00	100.00 <i>400</i>
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	850.00	0.00	850.00 <i>11 X</i>
7	1	To Dismantle and Refit Front Fender Glass.	60.00	0.00	60.00 <i>11 X</i>

Gross Labour Cost (\$\$) 1,330.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	To Supply Spray Terostat Sealant On The Cutting Areas.	50.00	0.00	50.00	X
2	1	To Carry-Out Body Cavity Preservation.	100.00	0.00	100.00	60
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,200.00	0.00	1,200.00	1000

Gross Labour Cost (\$\$) 1,350.00

< END OF ESTIMATES >

P- 3010.8
P- 2408.64
SW- 60.00
L- 1580.00

4048.64
3238