



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101010

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 17/02/2021
Reference CC6/FCI20010502/Upa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SML 6925A
Insured Veh. SHC 7180G
Claim No. D20003976MFSH
Policy No. D-18088937MFSH
Accident Date 27/09/2020
Inspection Date 01/10/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI20010502/Upa3q2	
			Date: 17/02/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7180G	Veh. Inspected	SML 6925A	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D20003976MFSH	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	01/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GB71080201	Colour	SILVER	
Odometer	147142 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	TOURADOR	6 mm	
L/H Front Tyre	185/65 R15	TOURADOR	6 mm	
R/H Rear Tyre	185/65 R15	TOURADOR	6 mm	
L/H Rear Tyre	185/65 R15	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2020	Inspection Date	01/10/2020	
Survey held at	YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 6925A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,050.40	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	440.20	-
1	FRONT FENDER EMBLEM LH	NECESSARY	65.90	65.90
1	FRONT DOOR LH	BENT / WARPED	950.40	950.40
1	FRONT DOOR INNER BOARD LH	NOT NECESSARY	680.40	-
1	FRONT DOOR LOCK LH	NOT NECESSARY	262.40	-
1	FRONT DOOR SIDE MIRROR LH	CRACKED	580.40	580.40
1	FRONT DOOR SIDE MIRROR COVER LH	CRACKED	98.20	98.20
1	FRONT DOOR SIDE MIRROR SIGNAL LAMP LH	CRACKED	330.50	330.50
1	FRONT DOOR HINGE TOP	NOT NECESSARY	59.40	-
1	FRONT DOOR HINGE BOTTOM	NOT NECESSARY	59.40	-
1	REAR DOOR LH	BENT / WARPED	985.40	985.40
1	REAR DOOR INNER BOARD LH	NOT NECESSARY	680.40	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	912.40	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	925.40	-
	LESS 20% DISCOUNT		-1,616.24	-602.16
			6,464.96	2,408.64
<u>SPECIAL NETT ITEMS</u>				
1	FRONT WHEEL RIM LH (SN)	NOT NECESSARY	400.00	-
1	REAR WHEEL RIM LH (SN)	NOT NECESSARY	400.00	-
1	FRONT TYRE LH (SN)	NOT NECESSARY	300.00	-
1	REAR TYRE LH (SN)	NOT NECESSARY	300.00	-
10	FRONT DOOR INNER BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
10	REAR DOOR INNER BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT LH WHEEL COVER (SN)	CUT	150.20	60.00
1	REAR LH WHEEL COVER (SN)	TO REPAIR SEE LABOUR	150.20	-
			1,800.40	60.00

Report Ref No. CC6/FCI20010502/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE AND REFIT REAR FENDER GLASS .	NOT NECESSARY	60.00	-
	TO DISMANTLE AND REFIT SLIDING DOOR GLASS . }		100.00	50.00
	TO TRANSFER SLIDING DOOR . }		80.00	-
	TO TRANSFER DOOR .		80.00	50.00
	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS.		100.00	20.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH ,FORNT BUMPER,REAR FENDER LH, REAR BUMPER AND REAR LH WHEEL COVER.		850.00	400.00
	TO DISMANTLE AND REFIT FRONT FENDER GLASS .	NOT NECESSARY	60.00	-
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	NOT NECESSARY	50.00	-
	TO CARRY -OUT BODY CAVITY PRESERVATION .		100.00	60.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,200.00	1,000.00
			2,680.00	1,580.00
GRAND TOTAL			10,945.36	4,048.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CC6/FCI20010502/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 6925A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 6925A

RE-INSPECTION

