

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20010513/AVF3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SKU2688L

Insured Vehicle No :

SKG8402D

Date of Loss: 30/09/2020

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU2688L**

Make & Model: SUBARU FORESTER, 2.0 (A)

Engine No: FA20K873180

Reg. Date: 20/07/2015 (Man. Year: 2015)

Chassis No: JF1SJGK85FG053362

Colour: Grey

Odometer: 100625 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,293.90	5,136.56	7,157.34	58.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,460.00	2,070.00	58.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,823.90	6,596.56	9,227.34	58.31
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	15,823.90	5,200.00	10,623.90	67.14

INSPECTION

Date of Assignment: 01/10/2020

Date Inspected: 01/10/2020 Inspected At:

1 KAKI BKT AVE 6 BLK C #01-43

Repairer: SM Automotive (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2020)
Parts:	M1-SUV	SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU2688L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H DOOR	Repair	920.80 F	*- FL
2	1		*FRONT L/H DOOR LOWER GARNISH	Cut	183.50 F	*183.50 FL
3	8		*FRONT L/H DOOR LOWER GARNISH CLIP	Necessary	52.00 F	*30.00 FL
4	1		*REAR L/H DOOR	Dented	880.40 F	*880.40 FL
5	1		*REAR L/H DOOR LOWER GARNISH	Cut	168.50 F	*168.50 FL
6	10		*REAR L/H DOOR LOWER GARNISH CLIP	Necessary	65.00 F	*30.00 FL
7	1		*REAR L/H DOOR INNER INSULATION	Necessary	550.00 FS	*300.00 FS
8	2		*REAR L/H DOOR HINGE	Not Necessary	82.00 F	*- FL
9	1		*REAR L/H DOOR LOCK	Not Necessary	290.50 F	*- FL
10	1		*REAR L/H DOOR WEATHERSTRIP	Not Necessary	220.50 F	*- FL
11	1		*REAR L/H DOOR ARCH RUBBER	Cut	229.00 F	*135.00 FL
12	1		*REAR L/H DOOR INNER TRIMBOARD	Cracked	490.50 F	*490.50 FL
13	1		*REAR L/H DOOR FRAMESTICKER	Necessary	120.80 FS	*50.00 FS
14	1		*REAR L/H DOOR WINDOW MOTOR & REGULATOR ASSY	Damaged	580.50 F	*235.00 FL
15	1		*REAR L/H FENDER	Repair	960.00 F	*- FL
16	1		*REAR L/H FENDER COWLING	Deformed	167.30 F	*167.30 FL
17	8		*REAR L/H FENDER COWLING CLIP	Necessary	52.00 F	*30.00 FL
18	1		*REAR L/H FENDER INNER TRIM BOARD	Not Necessary	408.10 F	*- FL
19	8		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
20	1		*REAR R/H LOWER ARM	Bent	493.20 F	*493.20 FL
21	1		*REAR R/H KNUCKLE ARM	Damaged	264.90 F	*264.90 FL
22	1		*REAR R/H KNUCKLE ARM BEARING	Necessary	261.00 F	*261.00 FL
23	1		*REAR R/H TRAILINK ARM	Bent	235.50 F	*235.50 FL
24	1		*REAR R/H CONTROL ARM	Bent	215.90 F	*215.90 FL
25	1		*SET REAR R/H SHOCK ABSORBER (COILOVER)	Bent	2,000.00 FS	*800.00 FS
26	1		*REAR R/H TYRE	Cut	550.00 FS	*250.00 FS
27	1		*SET REAR R/H RIM	Cut	1,800.00 FS	*680.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,293.90	5,900.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	764.14
Total Parts (\$\$)	12,293.90	5,136.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR CUSHION	New	200.00	80.00
2	TO REMOVE & REFIT REAR R/H FENDER GLASS	New	100.00	0.00
3	GUM	New	50.00	0.00
4	TO REMOVE & REFIT REAR R/H UNDERCARRIAGE	New	380.00	220.00
5	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
6	TO CHECK WIRING	New	100.00	30.00
7	TUFF KOTE	New	150.00	50.00
8	PANEL BEATING	New	1,200.00	500.00
9	SPRAY PAINTING	New	1,200.00	500.00
Gross Labour Cost (\$)			3,530.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >