

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20010515/AQF3Q2

**Date:** 25/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800002589

**Claimant**  
**Vehicle No :** SBX136S **Insured Vehicle No :** SGR1688G

Date of Loss: 21/09/2020 Nature of Claim: TP Claim No: 3173633722SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBX136S</b>	Engine No:	3GR0250367
Make & Model:	TOYOTA LEXUS GS300 AUTO, 3.0 (A)	Chassis No:	JTHBH96S205062547
Reg. Date:	15/09/2008 (Man. Year: 2008)	Odometer:	254425 km
Colour:	Black		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,469.48	4,489.20	5,980.28	57.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	480.00	1,170.00	70.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>12,119.48</b>	<b>4,969.20</b>	<b>7,150.28</b>	<b>59.00</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,900.00</b>		
<b>Nett Amount (\$\$)</b>	<b>12,119.48</b>	<b>3,900.00</b>	<b>8,219.48</b>	<b>67.82</b>

### INSPECTION

Date of Assignment: 01/10/2020

Date Inspected: 01/10/2020 Inspected At:

T & C Automotive (HQ)  
1 KAKI BUKIT AVE 6,, #01-49,  
AUTOBAY  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,061.25 FL	*1,061.25 FL
2	1		*FRONT BUMPER RH RETAINER	Not Necessary	75.40 FL	*- FL
3	1		*FRONT BUMPER LH RETAINER	Not Necessary	75.40 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	591.60 FL	*- FL
5	1		*SET HEADLAMP HID RH	Cut	2,054.75 FL	*2,054.75 FL
6	1		*SET HEADLAMP HID LH	Not Necessary	2,054.75 FL	*- FL
7	1		*HEADLAMP RH BRACKET	Not Necessary	171.40 FL	*- FL
8	1		*HEADLAMP LH BRACKET	Not Necessary	171.40 FL	*- FL
9	1		*HEADLAMP RH BALLAST	Not Necessary	781.40 FL	*- FL
10	1		*HEADLAMP RH CHROME	Cut	371.85 FL	*371.85 FL
11	1		*HEADLAMP LH CHROME	Not Necessary	371.85 FL	*- FL
12	1		*HEADLAMP RH WASHER CHROME (COVER)	Not Necessary	512.35 FL	*- FL
13	1		*HEADLAMP RH SPRAY NOZZLE (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*HEADLAMP SPRAY NOZZLE RH BRACKET	Not Necessary	61.10 FL	*- FL
15	1		*FRONT RH FENDER	Not Necessary	781.45 FL	*- FL
16	1		*FRONT GRILLE BASE	Cut	581.90 FL	*581.90 FL
17	1		*FRONT GRILLE CHROME	Cut	561.60 FL	*561.60 FL
18	1		*FRONT GRILLE LEXUS LOGO	Necessary	171.45 FL	*171.45 FL
19	1		*FOG LAMP RH	Cracked	85.20 FL	*85.20 FL
20	1		*BONNET RUBBER	Not Necessary	121.10 FL	*- FL
21	10		*FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
22	8		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	48.00 FS	*- FS
23	1		*FRONT NUMBER PLATE	Cracked	40.00 FS	*30.00 FS
24	1		*FRONT NUMBER PLATE CASING	Cut	180.00 FS	*30.00 FS
25	1		*FRONT RH SPORTS RIM	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,535.20</b>	<b>4,978.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,065.72	488.80
<b>Total Parts (\$\$)</b>	<b>10,469.48</b>	<b>4,489.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REWIRNG REFOCUS HEADLAMP	New	100.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE,TO CUT AND WELD,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	700.00	200.00
3	PUTTY AND SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	800.00	250.00
4	ANTI-RUST UNDERCOAT	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,650.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >