

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20010521/AGTF3Q2

Date: 26/10/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713MKF
Claimant		
Vehicle No : YN9120H	Insured Vehicle No :	SLL8980M
Date of Loss: 29/09/2020	Nature of Claim: TP	Claim No: 629275

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN9120H		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)	Engine No:	4P10B76376
Reg. Date:	31/08/2015 (Man. Year: 2015)	Chassis No:	FEB21EA10354
Colour:	White	Odometer:	156795 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,645.60	1,378.00	7,267.60	84.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	990.00	1,710.00	63.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,345.60	2,368.00	8,977.60	79.13
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	11,345.60	1,900.00	9,445.60	83.25
+ GST 7.00/7.00% (S\$)	794.19	133.00	661.19	83.25
Nett Amount (S\$)	12,139.79	2,033.00	10,106.79	83.25

INSPECTION

Date of Assignment:	01/10/2020	
Date Inspected:	02/10/2020 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Oct 2020)	
Parts:	N/A	mitsubishi CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN9120H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	2,550.00 F	*- FL
2	1		*REAR TAILGATE MITSUBISHI STICKER	Not Necessary	85.00 F	*- FL
3	1		*REAR TAILGATE 60KM/H STICKER	Not Necessary	20.00 F	*- FL
4	1		*REAR TAILGATE 18 PAX STICKER	Not Necessary	20.00 F	*- FL
5	1		*REAR TAILGATE LOWER MEMBER	Repair	1,500.00 F	*- FL
6	4		*REAR TAILGATE HINGE	Not Necessary	724.80 F	*- FL
7	2		*REAR TAILGATE SIDE RUBBER STOPPER	Not Necessary	62.40 F	*- FL
8	2		*REAR TAILGATE SIDE LOCK	Not Necessary	418.20 F	*- FL
9	1		*REAR TAILLAMP	N/s Cut	736.40 F	*286.00 FL
10	1		*REAR TAILLAMP PANEL	N/s Bent	748.80 F	*123.00 FL
11	1		*REAR NUMBER PLATE LAMP	Cracked	80.00 F	*55.00 FL
12	1		*REAR REINFORCEMENT	Bent	1,500.00 FS	*900.00 FS
13	1		*REAR REINFORCEMENT STICKER	Necessary	150.00 FS	*100.00 FS
14	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,645.60	1,494.00
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	116.00
Total Parts (\$)	8,645.60	1,378.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	100.00	30.00
2	TUFF KOTE	New	200.00	60.00
3	PANEL BEATING	New	1,000.00	400.00
4	SPRAY PAINTING	New	1,400.00	500.00
Gross Labour Cost (\$\$)			2,700.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >