



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103228

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 10/05/2021
Reference CC4/FCI20010524/Krs3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLC 5470K
Insured Veh. SHC 2548M
Claim No. D20003931MFSH
Policy No. D-20094922MFSH
Accident Date 28/09/2020
Inspection Date 02/10/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI20010524/Krs3q2 Date: 10/05/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2548M	Veh. Inspected	SLC 5470K
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003931MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	01/10/2020
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BM42A8G0339213	Colour	METALLIC RED
Odometer	47720 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	8 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	8 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	8 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/09/2020	Inspection Date	02/10/2020
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 5470K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED / DENTED	996.70	996.70
1	REAR BUMPER TOW COVER LH	MISSING	16.50	16.50
1	REAR BUMPER SIDE RETAINER LH	CRACKED	38.00	38.00
12	REAR BUMPER CLIPS	NECESSARY	36.00	36.00
1	REAR BUMPER REINFORCEMENT	BENT	564.20	564.20
2	REVERSE SENSOR INNER LH & RH	SERVICEABLE	407.20	-
1	REVERSE SENSOR HOLDER	SERVICEABLE	72.80	-
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	160.70	-
1	REAR FENDER COWLING LH	SERVICEABLE	153.10	-
4	REAR FENDER COWLING CLIPS	NOT NECESSARY	12.00	-
1	TAILAMP LH	SERVICEABLE	866.80	-
	LESS 20% DISCOUNT		-664.80	-330.28
			2,659.20	1,321.12
LABOUR				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING .		40.00	10.00
	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS.		60.00	50.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD ,TO KNOCK & REPAIR END PANEL ,RR FENDER LH INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF REAR BOOT LOCK .		500.00	200.00
	TO SPRAY REAR BUMPER ,REAR FENDER LH ,AND PANEL.		600.00	220.00
			1,260.00	480.00
GRAND TOTAL			3,919.20	1,801.12



RECOMMENDED COST OF REPAIRS			1,801.12
------------------------------------	--	--	-----------------

Report Ref No. CC4/FCI20010524/Krs3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 5470K

INSPECTION








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 5470K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

