

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20010530/GPA3Q2

**Date:** 20/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100423168

**Claimant**  
**Vehicle No :** SKC4349Y **Insured Vehicle No :** SKU6065H

Date of Loss: 30/09/2020 Nature of Claim: TP Claim No: 0271313287SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKC4349Y</b>	Engine No:	2ZRA729951
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W905001886
Reg. Date:	26/08/2011 (Man. Year: 2011)	Odometer:	266834 km
Colour:	Brown		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Double Star 6 mm	Rear Left Side:	Double Star 6 mm
Front Right Side:	Double Star 6 mm	Rear Right Side:	Double Star 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,439.92	2,222.60	1,217.32	35.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,460.00	1,140.00	43.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,039.92</b>	<b>3,682.60</b>	<b>2,357.32</b>	<b>39.03</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,950.00</b>		
<b>(\$\$)</b>	6,039.92	2,950.00	3,089.92	51.16
<b>+ GST 7.00/7.00% (\$\$)</b>	422.79	206.50	216.29	51.16
<b>Nett Amount (\$\$)</b>	<b>6,462.71</b>	<b>3,156.50</b>	<b>3,306.21</b>	<b>51.16</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>3,463.95</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>3,460.00</b>		

### INSPECTION

Date of Assignment: 01/10/2020

Date Inspected: 01/10/2020 Inspected At:

Wei Lee Motor Works (HQ)  
BLOCK 9 SIN MING INDUSTRIAL  
ESTATE #01-32  
Singapore 575644

Estimated Period of Repair: 5.0 days

---

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,175.00 FL	*1,175.00 FL
2	2		*TAILGATE SUPPORT ABSORBER	Not Necessary	494.90 FL	*- FL
3	1		*TAILGATE REFLECTOR	Not Necessary	277.60 FL	*- FL
4	1		*TAILGATE OUTER CHROME HANDLE	Not Necessary	252.10 FL	*- FL
5	1		*TAILGATE -TOYOTA LOGO	Necessary	70.20 FL	*70.20 FL
6	1		*TAILGATE LOCK	Bent	361.60 FL	*361.60 FL
7	1		*REAR BUMPER	Deformed	491.90 FL	*491.90 FL
8	2		*REAR BUMPER RETAINER -BELOW TAILLAMP	Not Necessary	80.80 FL	*- FL
9	2		*REAR BUMPER RETAINER RETAINER SIDE	Not Necessary	184.60 FL	*- FL
10	1		*END PANEL	Buckled	453.90 FL	*453.90 FL
11	1		*END PANEL TOP GARNISH	Not Necessary	253.10 FL	*- FL
12	1		*TAILGATE KEY SENSOR	Damaged	144.20 FL	*144.20 FL
13	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
14	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,499.90</b>	<b>2,896.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,059.98	674.20
<b>Total Parts (\$)</b>	<b>3,439.92</b>	<b>2,222.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE/TRANSFER REAR WINDSCREEN GLASS TO NEW DOOR	New	180.00	100.00
2	TO TRANSFER REAR DOOR BOARD ,REAR WIPER MOTOR N ALL ATTACHMENTS TO NEW DOOR	New	120.00	60.00
3	TO REMOVE DAMAGED PARTS AND ATTACHMENTS CUT N WELD DAMAGED PANEL REPAIR /RESHAPE DENTED AREAS REPLACE /ALIGN ALL PARTS INTO POSITION	New	1,300.00	600.00
4	TO SPRAY PAINT	New	1,000.00	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,600.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >