

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 209436/00J

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

01,OCT 2020

AIG Asia Pacific Insurance PL
78 Shenton Way
AIG Building
#07-16
S 079120

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SKU6065H
Accident involving vehicle no: SKC4349Y/SKU6065H
DOA: 30092020 AT Ang Mo Kio Ave 3

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SKC4349Y

To supply--

Description	Qty	Amount	
Tailgate / BNC	1	1,175.00	✓
Tailgate support absorber X @217.45	2	494.90	X
Tailgate reflector X	1	277.60	X
Tailgate outer chrome handle X	1	252.10	X
Tailgate-TOYOTA logo / MC.	1	70.20	✓
Tailgate lock / BT.	1	361.60	✓
Rear bumper / DE	1	491.90	✓
Rear bumper retainer-below taillamp X @40.40 (NN)	2	80.80	X
Rear bumper retainer retainer side X @92.30	2	184.60	X
End panel / BNC	1	453.90	✓
End panel top garnish X NN	1	253.10	X
Tailgate key sensor / DM	1	144.20	✓
Parts		4,239.00	
Parts less 25%		1,059.90	
		3,179.93	

2696.8

2022.6

File no: SKC4349Y

Reverse sensor

/ PM.

220.00 200

Rear number plate

X NN

40.00 X

To remove/transfer rear windscreen glass to new door

180.00 100

To transfer rear door board, rear wiper motor n all attachments to new door

120.00 60

To remove damaged parts and attachments

Cut n weld damaged panel

Repair/reshape dented areas

1,300.00 600

Replace/align all parts into position

1,000.00 ~~600~~ 700

To spray paint

6,039.93 1660

3682.6

-20%: 2950

5 Days.

Guo Qiang @ lk auto.com

82880282

lump sum repair.

After repair photos.

01/10/2020.