

ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim	TP	Vehicle No.	SLP4074J
-		Make & Model	MAZDA3 4-DOOR SEDAN 1.5L
		Year of Manufacture :	2017
		Chassis No.	JM6BN22A8H0146316
Ins Company : INC	DIA VS CHINA TAIPING	Engine No.	P520434045
Excess :	•	Policy No. :	•
Date of Accident :	24.09.2020	Time of Accident :	17:10
Suggested Days of Repair		In-house Vehicle Assess	<u>or</u>
Repair Estimate	7	Case Owner :	
Parts (a) Cost / List Price Plus/Less	\$ 84.00 List \$ 336.00 \$ -	Signature Contact No Spark Car Care Service 63837103 – Patrick Tia PatrickTia@sparkcarcare.cc 63837730 - Brenda Ng BrendaNg@sparkcarcare.cc 63837466 – Rohani RohaniM@sparkcarcare.co Workshop Operation 63837656 - Ngo Toh Wee Ngotw@sparkcarcare.com 63838115 - William Wang WilliamWangKS@sparkarc 63837362 - Andrew Goh AndrewCorneliusGoh@spa	om om m are.com
		Andrew Cornelius Con(@spa	ikcarcare.com
Total Repair Cost	\$ 1,686.00		
The above total will be sub	bjected to 7% G.S.T.		

Name of Surveyor	auo Qiang	82880282
Company	_ ckk	
Survey conducted on	atat	
Remarks By Surveyor	(before part of A
(a) The repair of this vehicle is	authorized / is not authorized until further notice	e. , , ,
(b) Recommended Days of Rep	pair :day(s)	8/0
(c) Resurvey	: Required / Not Required	/ / ·
(d) Excess	:\$	
(e) Signature of surveyor	: Date	::

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	:	SLP4074J	Case Owner	:	0
Make & Model	:	MAZDA3 4-DOOR SEDAN	Year Manufacture	:	2017
Chassis No	:	JM6BN22A8H0146316	Engine No	:	P520434045
Sales Order	:		Supplier	:	
Order By	:		Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper retainer LH / U	1		\$ 19.70			
	Front bumper retainer RH X VV	1		\$ 19.70			
	Front bumper clips / MC	10		\$ 30.00			
4	LH front fender / buc.	1		\$ 350.60		- Ma 12	
5	0	1					
6	0	1				77	
7	0	1					
8	0	1					
9	0	1					
10	0	1					4
11	0	1					
12	0	1					
13	0	1					
14	0	0					
15	0	0	- 2				
16	0	0	LIVE	Auto		,	
17	0	0	the	Auto Consultant Repairer of the for	hence notify		
18	0	0	• To	Bellinton par	owing:		
19	0	0	• To d	splay damaged part(s) during resurvey		
20	0	0	• Third	party survey in	confirmation		
21	0	0	No il	egal modification(s)	allowed	Pasis	1
22	0	0	is sui	lementary item(s) mi ject to final arr ova	at be resurveyed an	4	
23	0	0	Action	100	rom Insurance Con	pany	
24	0	0	Signatu	ledged by Repairer			
25	0	0	Date:				
-	0	0	ŝ.				
-	0	0				(V)	
-	0	0			-	-	
_		+		-			
30		0	* u			22.5	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284.62815767

Labour

Vehicle No.	:	SLP4074J	Case Owner	:	0
Make & Model	:	AZDA3 4-DOOR SEDAN 1.5L	Year of Manufacture	:	2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	Labour charges to repair and panel beat the front bumper	\$480.00	340.
	and replace damaged parts.		360.
2	To putty, apply primer & spray-paint the front bumper, RH front fender, RH front wheel rim and affected areas.	\$750.00	500
3	To check/re-set steering geometry and wheel alignment.	\$120.00	80.

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.