Spark Car Care
ComfortDelgro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bill To : CHINA TA	A <i>IPING</i> Vehi	cle Number	SLP4074J		
Attn to LKK - GUC	O QIANG Type	Of Claim	TP		
A. Spare parts	\$ 400.30	F. Total Parts	\$ 320.24		
B. Supplementary	_ \$	G. Total Labour	\$ 940.00		
C. Nett Price	\$ -	H. Total Repair	\$ 1,260.24		
D. Supp Nett Price	\$ -	I. Excess			
E. S/Nett		P/P Total	1,260.24		
Total Spare Parts Price	\$ 400.30				
Cost plus / List Down 20%	320.24	Lump Sum Less20%	6 \$ 252.05		
Total Nett Price Nett Price Less	\$ - \$ -	Lump Sum Rounding	\$ 1,008.19 \$ 1,000.00		
Total		Total Finalized	\$ 1,000.00		
N.B. If we DO NOT receive your	r reply within 2 weeks, we shall	treat the above finalized amount o	as confirmed L correct.		
Remarks : Please comfirm and revert	by Fax or Email				
Date In :	Total Repair Day				
Date Survey :	LOU/ Day				
Date Out	Total LOU _				
Sat/Sun/Ph. :	Rental/Day				
Authorized Repair Day 4	Total Rental				
Submitted By / Date : WILLIAM WANG 07 10 2020	Confirmed By / Date :				

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	: <u>S</u>	LP4074J	Case Owner	•	0
Make & Model	: <u>N</u>	IAZDA3 4-DOOR SEDAN	Year Manufacture	:	2017
Chassis No	: <u>J</u>	M6BN22A8H0146316	Engine No	1,	P520434045
Sales Order	1_		Supplier		
Order By	×.		Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY	Cost		List	Nett		Disposition By
	T are bescription	Q11	Price		Price	Price	S/N	Surveyor
1	Front bumper retainer LH	1		\$	19.70			
2	Front bumper retainer RH	1						
3	Front bumper clips	10		\$	30.00			
4	LH front fender	1		\$	350.60			
5	0	1 1						
6	0	1 1						
7	0	1						
8	0	1						
9	0	1						
10	0	1						
11	0	1						
12	0	1						
13	0	1						
14	0	0						
15	0	0						
16	0	0						
17	0	0						
18	0	0						
_	0	0						
20	0	0						
-	0	0		1				
22	0	0						
_	0	0						İ
	0	0		1				
	0	0		1				
_	0	0						
-	0	0						
_	0	0						
-	0	0						
-	0	0		İ				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

<u>Labour</u>

Vehicle No.	:	SLP4074J	Case Owner	•	0	
Make & Model	:	AZDA3 4-DOOR SEDAN 1.5L	Year of Manufacture		2017	

S/No	Labour Description	Esimated Price	Adjusted Price	
1	Labour charges to repair and panel beat the front bumper and replace damaged parts.	\$480.00	\$ 360.00	
2	To putty, apply primer & spray-paint the front bumper, RH front fender, RH front wheel rim and affected areas.	\$750.00	\$ 500.00	
3	To check/re-set steering geometry and wheel alignment.	\$120.00	\$ 80.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.