

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 547189

Mobile: 9061 0543 Email: mirage1195@gmail.com

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 450M1019.SH
Vehicle no : FBO4583U

1 REFERENCE

Date of inspection : 24 October 2019
Requested by : Law Chee Ming
Blk 780C Woodlands Crescent
#15-47
Singapore 733780
Type of survey : Independent
Repairer : Soon Hin Motors Pte Ltd
Blk 1018 Yishun Industrial Park A, #01-342, Singapore 768760
Date of accident : 14 October 2019

2 VEHICLE DATA

Make/model : **YAMAHA CZD300A / XMAX300**
Chassis no : MH3SH0848KK008025
Engine no : H336E0060529
Date of registration : 09 Oct 2019
Engine capacity : 292 cc
Colour : Matt Black
Odometer reading : 1803 km

3 STATIC CONDITION CHECK

Steering : Affected
Foot brakes : Serviceable
Hand brakes : Affected
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>mm/Make</u>	<u>SIZE</u>
Front tread	: 6 mm/Dunlop	120/70-15
Rear tread	: 6 mm/Dunlop	140/70-14

5 BRIEF DESCRIPTION OF DAMAGE

Front forks bent, front wheel rim bent/wobbled, front brake disc bent, LH & RH side fairing cover grazed, headlamp abraded, LH winker light scraped, RH side mirror abraded, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : **\$2,600.00** (lump sum)
Estimated no of days : **Four (4)**

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 450M1019.SH
Vehicle no: FBO4583U

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount	
Exhaust muffler cover /scr	1	scraped	120.00	120.00	✓
RH rear side cover set /scr	1	abraded	195.00	195.00	✓
RH rear side cover cover "X-MAX" /Nec	1	necessary	58.00	58.00	✓
LH side winker light Xsvc	1	scraped	68.00	68.00	X
Side mirror /scr	1	abraded	180.00	180.00	✓
Front cowling /scr	1	grazed	105.00	105.00	✓
LH side fairing cover /scr	1	grazed	128.00	128.00	✓
LH side fairing cover "Yamaha" logo /Nec	1	necessary	38.00	38.00	✓
RH side fairing cover /scr	1	dented/scraped	128.00	128.00	✓
RH side fairing cover "Yamaha" logo /Nec	1	necessary	38.00	38.00	✓
Headlamp assy /scr	1	abraded	295.00	295.00	✓
RH LH side step board /scr	1	cut/scraped	90.00	90.00	✓
LH belly cover Xsvc	1	grazed	60.00	60.00	X
Front brake disc Xsvc	1	bent	120.00	120.00	X
Front wheel rim Xsvc	1	bent/wobbled	350.00	350.00	X
Front fork assy LH/RH Xsvc	2	bent	520.00	520.00	X
RH side fairing top cover set Xsvc	1	scraped	85.00	85.00	X
Subtotal of the above			2,578.00	2,578.00	1,375.00
Discount 10%			257.80	257.80	-10%
Subtotal 1:			2,320.20	2,320.20	1,237.50
Rear box /scr	1	abraded/reflector broken	220.00	220.00	✓
Subtotal 2:			220.00	220.00	220
Total cost of parts:			2,540.20	2,540.20	

B LABOUR

Towing fee (2x)X	70.00	60.00	✓
Labour charges.	750.00	600.00	250
Total cost of labour:	820.00	660.00	250
Total cost of repair:	3,360.20	3,200.20	

Repair day - 3 days

L/S
\$1,350
3 days

1,237.50
220
250
1,707.50
-20%
1,366

Report no: 450M1019.SH
Vehicle no: FBQ4583U

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is \$3,200.20

(a) However, the recommended cost of repair based on lump sum basis would be \$2,600.00

(b) The estimated number of days for the repairs would be Four (4)
(1st re-inspection conducted on 4 February 2020)
(Post Repair Inspection conducted on 6 February 2020)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Prepared by:


.....
Liaw Leong San
Licensed Automotive Appraiser

Dated: 4 July 2020