



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19018669/Qsd3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 20-11-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 8719M	Veh. Inspected	FBQ 4583U
Policy No.	D18MCV0000143_01	Coverage (\$)	0.00
Claim No.	MCV2019D0001260	Excess (\$)	0.00
Assign From	CARINE KHEK	Assign Date	01/10/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA XMAX300	c.c	292
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3SH0848KK008025	Colour	BLACK
Odometer	1803	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	170/70-14	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	170/70-14	DUNLOP	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/10/2019	Inspection Date	24/10/2019
Survey held at	SOON HIN BLK 1018 #01-342 YISHUN INDUSTRIAL PARK A. SINGAPORE 768760		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------