

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010538/ERA3Q2
Date: 08/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900248795
Claimant Vehicle No :	SHD4728S	Insured Vehicle No :	SGG4004T
Date of Loss:	30/09/2020	Nature of Claim:	TP
		Claim No:	2359722560SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4728S		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU409087
Reg. Date:	16/01/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU189998
Colour:	Blue	Odometer:	66099 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,630.06	7,523.60	4,106.46	35.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,430.00	690.00	32.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,750.06	8,953.60	4,796.46	34.88
+ GST 7.00/7.00% (S\$)	962.50	626.75	335.75	34.88

Nett Amount (S\$)	14,712.56	9,580.35	5,132.21	34.88
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$62.60/day) (S\$)		313.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		10,150.84		

INSPECTION

Date of Assignment: 01/10/2020

Date Inspected: 01/10/2020

Estimated Period of Repair: 4.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	418.30 FL	*418.30 FL
2	1		*FRONT BUMPER BRACKET TOP RH	Broken	35.00 FL	*35.00 FL
3	1		*FRONT BUMPER BRACKET RH	Not Necessary	28.00 FL	*- FL
4	1		*FRONT BUMPER SIDE BRACKET SUPPORT RH	Broken	12.00 FL	*12.00 FL
5	1		*FRONT BUMPER CENTRE MOULDING	Broken	188.00 FL	*188.00 FL
6	1		*FRONT BUMPER GRILLE RH	Not Necessary	186.90 FL	*- FL
7	1		*FRT BUMPER REINFORCEMENT	Not Necessary	1,075.10 FL	*- FL
8	1		*FRT BUMPER TOWING COVER	Not Necessary	29.00 FL	*- FL
9	1		*FRT BUMPER LIP	Not Necessary	35.10 FL	*- FL
10	1		*FRT BUMPER LICENSE PLATE	Not Necessary	17.40 FL	*- FL
11	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
12	1		*RADIATOR GRILLE	Broken	1,409.10 FL	*1,409.10 FL
13	1		*RADIATOR GRILLE UPR	Not Necessary	48.30 FL	*- FL
14	1		*BONNET	Not Necessary	2,253.80 FL	*- FL
15	1		*FLAP ASSY ACTIVE AIR UPPER RH	Broken	356.00 FL	*356.00 FL
16	1		*FRONT BUMPER PLATE GARNISH	Not Necessary	188.00 FL	*- FL
17	1		*DAY LIGHT RH	Not Necessary	642.50 FL	*- FL
18	1		*HEADLAMP RH	Broken	1,993.65 FL	*1,993.65 FL
19	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	949.30 FL	*949.30 FL
20	1		*FRONT FENDER RH	Dented	490.70 FL	*490.70 FL
21	1		*REAR BUMPER	Broken	459.40 FL	*459.40 FL
22	10		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
23	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
24	2		*REAR BUMPER REFLECTOR LAMP LH RH	Not Necessary	63.80 FL	*- FL
25	1		*REAR BUMPER CENTRE MOULDING ASSY	Cut	451.25 FL	*451.25 FL
26	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Not Necessary	155.00 FL	*- FL
27	1		*REAR FOG LAMP	Not Necessary	201.50 FL	*- FL
28	1		*FRT NUMBER PLATE WITH TRIM COVER	Crushed	55.00 FS	*55.00 FS
29	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
30	1		*REAR NUMBER PLATE WITH TRIM	Cut	55.00 FS	*25.00 FS
31	1		*REVERSE SENSOR	Shorted	180.00 FS	*180.00 FS
32	1		*EMBLEM LONIQ	Not Necessary	31.30 FS	*- FS
33	1		*EMBLEM -BLUE DRIVE	Not Necessary	26.60 FS	*- FS
34	1		*RADIATOR BLOWER	Broken	576.00 FL	*576.00 FL
35	1		*RADIATOR ASSY	Broken	510.50 FL	*510.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*RADIATOR ASSY INVERTER	Bent	884.80 FL	*884.80 FL
37	2		*COOLANT (LIT)	Necessary	12.00 FS	*12.00 FS
38	1		*TUBE LIQUID	Bent	224.00 FL	*224.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)**14,435.10****9,324.00****- List Item Discount on L Items 20.00/20.00% (\$)**

2,805.04

1,800.40

Total Parts (\$)**11,630.06****7,523.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	640.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	REMOVE/REPLACE REVERSE SENSOR	New	120.00	30.00
4	REMOVE /INSTALL RADIATOR & AIRCON CONDENSER	New	150.00	100.00
5	TUFF KOTE	New	90.00	30.00
6	CHECK LIGHTING	New	60.00	30.00
Gross Labour Cost (S\$)			2,120.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >