

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010543/ACD3E2

Date: 10/03/2021

REFERENCE

Insured/Claimant:	NICOLAE SASARAN	Policy No:	2070054141		
Date of Loss:	30/09/2020	Nature of Claim:	OD	Claim No:	2495456535SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS9563D	Engine No:	CHZC34759
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Chassis No:	WAUZZZ8V1LA004278
Reg. Date:	23/03/2020 (Man. Year: 2019)	Odometer:	5909 km
Colour:	Black		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R15	Rear Tyre Size:	205/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,489.00	8,344.96	9,144.04	52.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,672.00	3,372.00	3,300.00	49.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,161.00	11,716.96	12,444.04	51.50
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	23,561.00	11,116.96	12,444.04	52.82
+ GST 7.00/7.00% (S\$)	1,649.27	778.19	871.08	52.82
Nett Amount (S\$)	25,210.27	11,895.15	13,315.12	52.82

INSPECTION

Date of Assignment:	01/10/2020		
Date Inspected:	01/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	38.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	159.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	530.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	293.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM - RH	Cut	161.00 FS	*128.40 FS
8	1		*WHEEL HOUSING LINER ADAPTER - RH	Not Necessary	37.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cut	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	189.00 FS	*150.80 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	186.00 FS	*- FS
12	1		*FRONT REINFORCEMENT BEAM	Not Necessary	715.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	187.00 FS	*149.60 FS
14	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
15	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
16	1		*SIGNAL HORN - RH LOW TONE	Not Necessary	197.00 FS	*- FS
17	1		*FRONT FENDER - RH	Buckled	841.00 FS	*672.80 FS
18	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - RH	Not Necessary	38.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - RH	Not Necessary	27.00 FS	*- FS
21	1		*FRONT FENDER BRACE	Bent	95.00 FS	*75.68 FS
22	1		*WHEEL HOUSING LINER - RH	Not Necessary	167.00 FS	*- FS
23	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
24	1		*BONNET	Repair	3,134.00 FS	*- FS
25	1		*BONNET ATTACHMENT PARTS	Not Necessary	163.00 FS	*- FS
26	2		*BONNET LID HINGE - LH / RH	Not Necessary	122.00 FS	*- FS
27	1		*BONNET CATCH HOOK	Not Necessary	89.00 FS	*- FS
28	1		*BONNET STRIKER - RH	Not Necessary	109.00 FS	*- FS
29	1		*BONNET EDGE PROTECTION	Not Necessary	28.00 FS	*- FS
30	1		*BONNET LID LOCK	Not Necessary	212.00 FS	*- FS
31	1		*LED HEADLIGHT - RH	Cracked	5,455.00 FS	*4,364.00 FS
32	1		*LIFT CYLINDER - RH	Not Necessary	141.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - RH	Not Necessary	24.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
35	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
36	1		*SUNDRIES	Necessary	200.00 FS	*12.80 FS
37	1		*FOAM FILLER PIECE COVER	Not Necessary	121.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 17,489.00 8,344.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,500.00	1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT DOOR AND RHS FRONT FENDER	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,672.00	3,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >