

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20010546/UBA3Q2**Date:** 07/12/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900006697
Claimant
Vehicle No : GBH3401R **Insured Vehicle No :** SMH3907T
Date of Loss: 30/09/2020 Nature of Claim: TP Claim No: 9342561306SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH3401R**
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2794074
Reg. Date: 27/04/2018 (Man. Year: 2018) Chassis No: JTFAT35Y40K210172
Colour: Silver Odometer: 107619 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)
Front Left Side: Longway 6 mm Rear Left Side: Yokohama 6/6 mm
Front Right Side: Longway 6 mm Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,617.00	1,859.10	757.90	28.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,395.00	1,020.00	375.00	26.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,012.00	2,879.10	1,132.90	28.24
+ GST 7.00/7.00% (S\$)	280.84	201.54	79.30	28.24
Nett Amount (S\$)	4,292.84	3,080.64	1,212.20	28.24
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
	Nett Liability (S\$)	3,480.64		
	Global Sum Settlement (S\$)	3,400.00		

INSPECTION

Date of Assignment: 08/10/2020
Date Inspected: 08/10/2020 Inspected At: Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	685.90 FL	*683.90 FL
2	1		*FRONT BUMPER RH BRACKET	Bent	271.30 FL	*271.20 FL
3	1		*FRONT GRILLE	Cracked	501.20 FL	*501.20 FL
4	1		*FRONT GRILLE SEAL	Necessary	27.40 FL	*27.40 FL
5	1		*RH FRONT HEADLAMP	O/S Cracked	1,950.20 FL	*975.10 FL
6	1		*NUMBER PLATE	Bent	40.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,476.00	2,473.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	859.00	614.70
Total Parts (\$\$)	2,617.00	1,859.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	780.00	600.00
2	LABOUR CHARGE	New	580.00	400.00
3	WIRING CHECK	New	35.00	20.00
Gross Labour Cost (S\$)			1,395.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >